

REPORT of SURVEY for REPAIRS.

Rec 15/3/69

No. in Reg. Book. **No. 10788** Survey held at Newcastle Date 8th Febry 18 69
 on the "S. S. Hurley" Master G. Stallett
 Tonnage 785 built at Newcastle When built 1866
 By whom built Palmer Owners Palmer & Co
 Port belonging to London Destined Voyage London
 If Surveyed Afloat or in Dry Dock Young's dry dock

Last Survey, No. 6140 Port Iron. Classified A. 1.
 3.68-

REPAIRS now done:

The vessel placed in dry dock, the cement in bottom examined by the removal of tank covers, and found in good condition, both surfaces of outside plating exposed, all oxidation removed, and the vessel repainted inside and outside.

Present Condition of the

Decks	<u>Good</u>	Birch	<u>Good</u>	Windlass and Capstan	<u>Good</u>
Waterways		Freemans		Pumps	
Comings		Breasthooks and Stemson		Boats	
Upper Deck Beams & Fastenings		Transoms, Pointers, and Crutches		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Timbers of the Frame at the openings		Condition, how ascertained	
Planksheers	<u>where</u>	Ditto Ditto at other places		Sails	<u>and</u>
Sheerstrakes		Keelsons	<u>where</u>	Anchors No. of	
Topsides		Clamps and Shelves		Cables	
Wales		Ceiling		Hawsers and Warps	
Plating		Rudder	<u>seen</u>	Standing & Running Rigging	<u>Sufficient</u>
Plank (Bottom) and Counter	<u>seen</u>	Copper	When put on		

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good where seen

This vessel has now been surveyed in accordance with the Rules for Iron Ships, Survey N^o 1. She is in good and efficient condition, and eligible, in my opinion, to remain as classed, and to be marked in the Register book - S.S. N^o 1. 69-

The Amount of Fee.....£ 4 : 7 : 7 is received by me,

Special..... 2 : 2 : 0

Certificate (if required) : : :

Committee's Minute 16th March 18 69

Character assigned A 1

S. S. No. 1 = 1/19 MMS



© 2019

Lloyd's Register
 IRON443-0392dation