

# REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No. 3446** Survey held at Leith Date 14<sup>th</sup> Feb<sup>y</sup>: 20<sup>th</sup> April 1869  
 154 on the Screw Steamer "Fingal" Master Robertson  
 Tonnage 464 built at Leith When built 1862  
 By whom built S. & H. Martin & Co. Owners London & Ant. Shipp<sup>y</sup> Co.  
 Port belonging to Leith Destined Voyage London  
 If Surveyed Afloat or in Dry Dock Dry Dock & Afloat

Last Survey, No. 3540 3951 Port Leith Iron Classed A. 1.  
 (S.S. No. 2-68.) 1-68

## REPAIRS

Now done. - Stern Frame new, Four Stern Plates new. Engines and Boilers with the Bearers new, Rudder repaired, Cemented in Bottom in Engine Room and After Hold spaces, Scraped and painted where necessary. - This Vessel is now all cemented, part having been done in 1868, and part now.

Certificate for Engine and Boilers appended herewith.

## Present Condition of the

Decks <u>In good condition</u>	Rivets <u>Good where run</u>	Windlass and Capstan <u>Good &amp; Sufficient</u>
Waterways <u>"</u>	Breasthooks and Stenson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frames at the openings <u>"</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Ditto Ditto at other places <u>"</u>	Condition, how ascertained <u>"</u>
Planksheers <u>"</u>	Keelsons <u>"</u>	Sails <u>"</u>
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	Anchors No. of <u>3 B. 1 S. 10</u>
Topsides <u>"</u>	Ceiling <u>"</u>	Cables <u>"</u>
Wales <u>"</u>	Rudder <u>"</u>	Hawsers and Warps <u>"</u>
Plating (Bottom) and Counter <u>"</u>	Copper <u>When put on</u>	Standing & Running Rigging <u>"</u>

## General Observations and Opinion.

Caulking of Bottom, Deck, & Waterways. Good where tried

This Vessel is in good and efficient condition, eligible in my opinion to remain as classed A. 1.


The Amount of Fee.....£ 2: 0: 0 is received by me,

Ex<sup>2</sup> RRB Special..... 2: 2: 0

Certificate (if required) £ 4: 2: 0

Committee's Minute 23<sup>rd</sup> April 18 69

Character assigned B 1

*record repair*  
  
 E. W. R. Buchanan

© 2019

Lloyd's Register Foundation

IRON444-0052