

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No. 21867** Survey held at Liverpool Date April 26 to May 22 1869
 on the Iron S "British Monarch" Master J. Rees
 Tonnage 1236 built at Burtonhead When built 1845 - 4 mo
 By whom built Clover Owners British S Owners Co
 Port belonging to Liverpool Destined Voyage India
 If Surveyed Afloat or in Dry Dock Tandon Graving & Tallhouse dock

Last Survey, No. 6775 Port Iron. Classed A-1

REPAIRS - Done in accordance with Survey No. 1

Nearly all the Ceiling in flat of bottom both sides fore & aft - lifted, all oxidation removed, the Cement found much wasted in places & has been renewed, & the Hull now painted where required -

Present Condition of the

Decks	Ironails <u>Reels</u>	Windlass and Capstan <u>Good & sufficient</u>
Waterways	Breasthooks and Stenson	Pumps <u>" "</u>
Comings	Transoms, Pointers, and Crutches	Boats <u>" "</u>
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c. <u>" "</u>
Lower Deck Beams & Fastenings	Ditto Ditto at other places <u>seen</u>	Condition, how ascertained <u>Seen from deck</u>
Planksheers	Keelsons	Sails <u>Good & sufficient</u>
Sheerstrakes	Clamps and Shelves <u>seen</u>	Anchors No. of <u>" "</u>
Topsides	Ceiling <u>Good where seen</u>	Cables <u>Good where seen</u>
Wales	Rudder	Hawsers and Warps <u>well found</u>
Plates	Cement Copper <u>Good</u> When put on <u>1845 - 4</u>	Standing & Running Rigging <u>" "</u>
Plank (Bottom) and Counter	Caulking of Bottom, Deck, & Waterways. <u>Satisfactory</u>	

Is now in an efficient condition & in my opinion eligible to remain as Classed & marked A-1 - 1869

The Amount of Fee.....£ - : - : is received by me,

Special..... 3 : 3 : " 25/5/69

Certificate (if required) " : 5 : "

Committee's Minute Liverpool 28th May 1869

Character assigned A-1 1869

Com. M. 69

Wheeler



© 2019

Lloyd's Register Foundation

IRON444 - 0147

REPORT OF THE COMMISSIONERS OF THE LAND OFFICE

For the year ending 31st March 1867

By order of the Board of Commissioners

Wm. Smith

James

John

John

John

REPAIRS

Particulars	Amount	Total
Repairs to the walls of the enclosure	£ 100 0 0	
Repairs to the gates of the enclosure	£ 50 0 0	
Repairs to the fences of the enclosure	£ 20 0 0	
Repairs to the drains of the enclosure	£ 10 0 0	
Repairs to the roads of the enclosure	£ 5 0 0	
Repairs to the buildings of the enclosure	£ 10 0 0	
Repairs to the tools of the enclosure	£ 5 0 0	
Repairs to the furniture of the enclosure	£ 5 0 0	
Repairs to the clothing of the enclosure	£ 5 0 0	
Repairs to the food of the enclosure	£ 5 0 0	
Repairs to the medicine of the enclosure	£ 5 0 0	
Repairs to the other articles of the enclosure	£ 5 0 0	
Total	£ 210 0 0	

British Museum



2019

Lloyd's Register Foundation