

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No. 9622** Survey held at Cardanlands Date March 25th to April 1st 1869
361 on the S.S. Seaton Iron Master R. Weatherley
 Tonnage 552 built at Newcastle When built 1857
 By whom built Owners M. Wood
 Port belonging to Sunderland Destined Voyage Coasting
 If Surveyed Afloat or in Dry Dock In Dry Dock

Last Survey, No. 9275 3946 Port Iron Sunderland Classed 3 A. Cont 66-5 12th 67

REPAIRS

At the present time, about 50 planks shifted in the Main Deck with Yellow Pine. Windlass unhooked & lining stripped. The Main Deck caulked & the Vessel painted & coated. A few rivets renewed.

Present Condition of the

Decks	Greenails <u>Rivets</u>	Windlass and Capstan <u>SH</u> <u>Good</u>
Waterways	Breasthooks and Stemson	Pumps <u> </u> <u> </u>
Comings	Transoms, Pointers, and Crutches	Boats <u> </u> <u> </u>
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c. <u> </u> <u> </u>
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained <u> </u> <u> </u>
Planksheers	Keelsons	Sails <u>Well found</u>
Sheerstrakes	Clamps and Shelves	Anchors No. of <u>3 Brs SH & Kops</u>
Topsides	Ceiling	Cables <u>Complete</u>
Wales	Rudder	Hawsers and Warps <u>Sufficient</u>
Plank (Bottom) and Counter	Copper	Standing & Running Rigging <u>Good</u>

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good

Is now in an efficient state and in my opinion entitled to remain as classed

Leithhouse Martindale

The Amount of Fee.....£ 2 : " : " is received by me,

Special..... 1 : 1 : "

Certificate (X required) " : 5 : "

Committee's Minute 8th June 18 69

Character assigned Cont' 5 A 1 WMS



© 2019

Lloyd's Register Foundation

IRON444-0159