

7132

30/11/69

## REPORT of SURVEY for REPAIRS.

No. in Reg. Book. 1070 No. 5249 Survey held at London Date 2nd June 18 69  
 on the  bark "Mountain Laurel"  Master John Henry Elbeck  
 Tonnage 690 built at Harrington When built 1865 - 2mo  
 By whom built Williamson Owners Spratt & Co  
 Port belonging to Liverpool Destined Voyage Kurrachee  
 If Surveyed Afloat or in Dry Dock timed in dry dock and afloat

Last Survey, No. 5249 Port Iron. Classed SA 1

## REPAIRS

The timber boards and ceiling equal to one stroke fore and aft on both sides removed.

Some of the rivets through the lower landing edges of the plating on each bow that were found wasted at their points have now been renewed. Rudder pintles refitted, bottom cleaned and coated with Paint and Sallow.

The following have now been tested. Viz:-

1 Bow Anchor & Shackle	25-1-20	No. 2881	Lloyd's public test	25-1-3	19 Mar. 1869.
1 Bow " "	26-1-8	No. 2882	" "	25-17-13	
135 1/4 fms. 1/2 chain cable	2502	" "	" "	44-0-0	21 Mar. 1869.
137 2/3 " " "	2503	" "	" "	40-10-0	

L.B. Ltd. Supot.

## Present Condition of the

Decks	Freemasts	Windlass and Capstan
Waterways	Rivets	Pumps
Comings	Breasthooks and Stowson	Boats
Upper Deck Beams & Fastenings	Transoms, Pointers, and Crutches	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Timbers of the Frame at the openings	Condition, how ascertained
Planksheers	Ditto Ditto at other places	Sails
Sheerstrakes	Keelsons	Anchors No. of
Topsides	Champs and Shelves	Cables
Wales	Ceiling	Hawsers and Warps
Plank (Bottom) and Counter	Rudder	Standing & Running Rigging
General Observations and Opinion,	Copper	Caulking of Bottom, Deck, & Waterways.

*These seen wood*  
*These seen wood*

Is now in good and efficient condition and in my opinion eligible to remain as Classed SA 1 and to be marked L.S. No. 1-69, (A & C.P.)

The Amount of Fee.....£ 2 : - : - is received by me,

Special.....£ 3 : 3 : - } A.G.

Certificate (if required) : 5 :

Committee's Minute 11th June 18 69

Character assigned A 1

L.S. No. 1-69



© 2019

Lloyd's Register Foundation

IRON444-0179