

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No. 21920** Survey held at Liverpool Date 20th Nov 1869
 on the Thos B^{ly} Tmay Master Campbell
 Tonnage 422 built at Glasgow When built 1861
 By whom built _____ Owners Tmay & Co.
 Port belonging to Liverpool Destined Voyage to Lima
 If Surveyed Afloat or in Dry Dock Canning Wharf and Salt House Dock

Last Survey, No. 5107 Port Im. Classed A1
 88 Nov 1-69

REPAIRS

of damage

The upper part of the stem renewed. Apron-plates fitted inside in the way of the same. Flanged & bolted, and riveted through, the hood end plating -

The bottom outside cleaned and coated

Present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats <u>And stuff</u>
Upper Deck Beams & Fastenings _____	Timbers of the Frame at the openings _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings <u>Where</u>	Ditto Ditto at other places _____	Condition, how ascertained <u>Where</u>
Planksheers _____	Keelsons <u>Where</u>	Sails _____
Sheerstrakes _____	Clamps and Shelves _____	Anchors No. of _____
Topsides _____	Ceiling _____	Cables <u>Seen</u>
Wales <u>Seen</u>	Rudder <u>Seen</u>	Hawsers and Warps _____
Plank (Bottom) and Counter _____	Copper <u>Seen</u> When put on <u>See for repairs</u>	Standing & Running Rigging _____

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

This vessel is now in good and efficient condition eligible to remain as classed A1

The Amount of Fee.....£ 1 : " : " is received by me,

Special..... 2 : 2 : " 1-0-0 10/14/69

Certificate (if required) " : " : "

Committee's Minute Liverpool 29 June 1869

Character assigned A1 - Repair damage/repair



© 2019

Lloyd's Register Foundation

IRON 444-0214

REPORT OF SURVEY FOR REPAIRS

Cheney
21.9.20



© 2019

Lloyd's Register
Foundation