

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 750 Survey held at London Date June 24th 18 69
 on the Iron Ship "Star of Erin" Master Simpson
 Tonnage 949 built at Belfast When built 1862
 By whom built Harland Owners Corry & Co
 Port belonging to Belfast Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Wigrams dry dock

Last Survey, No. 6492 Port Irish Classed # A1 (ts b5)
68

REPAIRS

Now done as per Rule for the Survey of Iron Ships Classed for a period of Years. Limber boards lifted and ceiling equal to three shakes fore and aft on both sides lifted and the cement and surfaces of outside plating when exposed found in good condition. Windlass shipped and unhooked, and chains ranged on deck. Bottom scraped and painted with 3 Coats of Composition paint.

Present Condition of the

Decks		Treenails		Windlass and Capstan	
Waterways		Breasthooks and Stemson		Pumps	<u>good</u>
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	<u>good</u>
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Condition, how ascertained	<u>Seen from deck</u>
Planksheers		Keelsons		Sails	<u>Sufficient</u>
Sheerstrakes		Clamps and Shelves		Anchors No. of	<u>3 15 24</u>
Topsides		Ceiling		Cables	<u>Sufficient</u>
Wales		Rudder		Hawsers and Warps	<u>good</u>
Plank (Bottom) and Counter		Copper When put on		Standing & Running Rigging	<u>good</u>
General Observations and Opinion,		Caulking of Bottom, Deck, & Waterways.		<u>good when seen</u>	

Is now in good order and Condition and eligible in my opinion to remain as classed and be marked (T.S. 69)

The Amount of Fee.....£ : : is received by me,

Special..... 3 : 3 : 68

Certificate (if required) : 5 : 68

Committee's Minute 16th July 18 69

Character assigned A 1 S. S. No 2-49



© 2019

Lloyd's Register Foundation

IRON444 - 0290