

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. *902* No. *Survey held at London* Date, first Survey *Aug 5* Last Survey *3 Sept. 1869*
on the *iron ship "Michael Scott"* Master *Penrellya*
Tonnage *1198* built at *London* When built *1864-4 mo*
By whom built *Peniel* Owners *Stilley & Co*
Port belonging to *London* Destined Voyage *Bombay*
If Surveyed Afloat or in Dry Dock *Went's lower dry dock and afloat.*
Last Survey, No. *5778* Port *Iron.* Classed *FAL 1*

REPAIRS, &c.

The timber boards and ceiling in flat of bottom, for about five feet on each side of the keelson, all fore and aft removed. The frames, Plating, Rivets &c. found all in good condition, and the Cement coating sound, and good, and adhering satisfactorily to the iron.

Scraped, and painted, from upper turn of bilge to lower deck stringer-plate, all fore and aft, on both sides. Bottom cleaned, and coated with Paint, and Perry's Composition.

140 fathoms. 12^{ms} Manila. No. 2074 "Hepburn" Ser. 72. 3rd July 1866. Reade Sup't.
Present Condition of the "Hepburn" Ser. 72. 6th Aug. 1869. Pitt f.

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stems	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper	Standing & Running Rigging
Engine Room Skylights	Caulking of	Cargo and Main Hatchways
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways	Hatches
General Observations and Opinion,		

I am in good and efficient condition
and in my opinion eligible to remain as Classed - FAH 1.
and be marked (S.S.A.) - b9,

The Amount of Entry Fee.....£ — : — is received by me.

Special..... 4 : 4

Certificate (if required)

Committee's Minute 24th September 1869

Character assigned

© 2019

IRON 444 - 0431

Recd. 2 w
Selling Certificate
1.10.69 N.Y.
on part of owned

RECEIVED FOR DELIVERY TO PROCEED



© 2019

Lloyd's Register
Foundation