

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 52 Survey held at London Date 16th to 23rd Aug^t 1869
 on the S. P. "Yanfield" Master G. Bowdell
 Tonnage 759 built at Newcastle When built 1864 12 Mo
 By whom built Palmer Owners Cory & Co
 Port belonging to London Destined Voyage London Coaster
 If Surveyed Afloat or in Dry Dock Victoria Pontoons

Last Survey, No. 6556 Port Iron. Classed A.1
 REPAIRS now done S.S. No. 1. by 9.68

Hold cleared, the Limbers, and Tank covers. Fore and Aft on both sides removed.

Renewed a few Keel rivets that were found wasted, recaulked all the Butts of Bottom plating. Inside scraped, and painted from Upper Deck stringer plate to turn of Bilge. Renewed twelve deck planks between Tunnel hatch, and Skylight on Poop. fitted new Stern tube & rebushed rudder braces. Bottom cleaned, and coated with paint and Tallow.

Present Condition of the

Decks	Greenails Rivets	Windlass and Capstan	Good
Waterways	Breasthooks and Stemson	Pumps	—
Comings	Transoms, Pointers, and Crutches	Boats	—
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.	—
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained	Seen from deck
Planksheers	Keelsons	Sails	—
Sheerstrakes	Clamps and Shells	Anchors No. of	Good
Topsides	Ceiling	Cables	and
Wales	Rudder	Hawsers and Warps	Sufficient
Plank (Bottom) and Counter	Copper <u>Asp</u> When put on <u>1864</u>	Standing & Running Rigging	—

General Observations and Opinion, Caulking of Bottom, Deck, & Waterways. Good where tested

Is now in good and efficient condition, and in my opinion eligible to remain as Classed, and to be marked S. S. No. 2. 69

The Amount of Fee.....£ : : is received by me,
 Special..... 2 : 2 :
 Certificate (if required) : : }

Committee's Minute 24th September 1869

Character assigned A.1 S. S. No. 2. by MAS



© 2019

Lloyd's Register Foundation

IRON444-0436