

ANNUAL SURVEYS.

No. 357 Survey held at London Date 23rd to 28th October 18 69
 on the Iron Barque "Golden Russet" Master H. H. Hull
 Tonnage 578 Built at Sunderland When built 1868. 8 mo.
 By whom built Self Owners Brown & Co
 Port belonging to Sunderland Destined Voyage Brisbane
 If Surveyed Afloat or in Dry Dock New Crane Dry Dock London Docks

Last Survey, No. 6587 Port of Iron Classed A. 1
 (9.68)

The present Condition of the

Decks	<u>Treenails</u> <u>Rivets</u>	Windlass and Capstan
Waterways	Breasthooks and <u>Stemson</u>	Pumps
Comings	<u>Transoms</u> , Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	<u>Timbers of the</u> Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	<u>Ditto</u> ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
<u>Plank</u> (Bottom) and Counter	<u>Copper</u> <u>Cement</u> When put on <u>1868</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Good

The bottom scraped, cleaned, and coated with two coats of Red and White Lead, and one coat of Tallow and Arsenic.

Is in good condition; and fit, in my opinion, to remain as classed (viz), A. 1.

Committee's Minute 2nd November 18 69

J. J. Bone

Character assigned A 1 (MA)

Certificate (if required).

No. 748 Survey held at London Date 26th October 18 69
 on the Iron Steamer "May Queen" Master J. Brown
 Tonnage 595 Built at London When built 1864. 3 mo.
 By whom built Lingley Owners Genl. A. J. Collier & Co
 Port belonging to London Destined Voyage Cardiff
 If Surveyed Afloat or in Dry Dock Princes Dry Dock

Last Survey, No. _____ Port of _____ Classed 6. A. 1
 (t. s. 67) (7.68)

The present Condition of the

Decks	<u>Treenails</u> <u>Rivets</u>	Windlass and Capstan
Waterways	Breasthooks and <u>Stemson</u>	Pumps
Comings	<u>Transoms</u> , Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	<u>Timbers of the</u> Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	<u>Ditto</u> ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
<u>Plank</u> (Bottom) and Counter	<u>Copper</u> <u>Cement</u> When put on <u>1864</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Good

The bottom cleaned, and coated with two coats of Coal Tar and Black Lead.

Is in good condition; and fit in my opinion to remain as classed (viz), 6. A. 1.

Committee's Minute 2nd November 18 69

J. J. Bone

Character assigned A 1 (MA)

Certificate (if required).