

20/2/69

7686

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No. 22179** Survey held at Liverpool Date 15 March 1869 Rec. 29/1/70
on the S.S. "GLADIATOR" Master J. Reynolds
Tonnage 59 1/2 built at Stockton When built 1860-9 mo
By whom built — Owners J. J. Harrison
Port belonging to Liverpool Destined Voyage S. America
If Surveyed Afloat or in Dry Dock Brunswick Dry dock and afloat.

Last Survey, No. 6361 Port Iron. Classed Q. A. 1.

REPAIRS now done Periodical Survey - Timbers and portion of ceiling examined
to examine Bottom - Caulking found good - Both surfaces of outside
plating exposed - and painted.

Present Condition of the

Decks	Present	Windlass and Capstan
Waterways	<u>good where seen</u>	<u>good and sufficient</u>
Comings	"	<u>where seen</u>
Upper Deck Beams & Fastenings	"	"
Lower Deck Beams & Fastenings	"	"
Planksheers	"	"
Sheerstrakes	"	"
Topsides	"	"
Wales	"	"
Blank (Bottom) and Counter	"	"
Breasthooks and Stemson	<u>good where seen</u>	"
Transoms, Pointers, and Orutches	"	"
Timbers of the Frame at the openings	"	"
Ditto Ditto at other places	"	"
Keelsons	"	"
Clamps and Shelves	"	"
Ceiling	"	"
Rudder	"	"
Copper	<u>Copper</u> When put on <u>when built</u>	"
Boats	"	"
Masts, Yards, &c.	"	"
Condition, how ascertained	<u>from deck</u>	"
Sails	"	"
Anchors No. of	"	"
Cables	"	"
Hawsers and Warps	"	"
Standing & Running Rigging	"	"

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

good where seen
This vessel is now in good and efficient condition and is eligible
to remain as classed. Q. A. 1. marked t.s. 69.

The Amount of Fee.....£ " : " : " is received by me,

Special..... 2 : 2 : 2

Certificate (if required) " : " : "

Committee's Minute Liverpool, 28th January 1870

Character assigned Q A 1 - (t.s. 69)



© 2019

Lloyd's Register
Foundation

IRON 445-0297

"Gladstone
-22.179-