

1914  
**ANNUAL SURVEYS.**

Rec 2/5/70

146 No. 3130 Survey held at Penfrew Date 10<sup>th</sup> April 1870  
 on the Screw S<sup>r</sup> "Kinsale" Master M<sup>r</sup> Keller  
 Tonnage 499 Built at Penfrew When built 1865 10 Mo  
 By whom built Henderson Owners Glasgow, Cork & Waterford S. S. Co.  
 Port belonging to Glasgow Destined Voyage Coaster  
 If Surveyed Afloat or in Dry Dock Henderson's Patent Slip

Last Survey, No. 7553 Port of North Classed A. 1<sup>st</sup> 11.68  
S. S. N<sup>o</sup> 1.68

The present Condition of the

|                               |  |                                     |
|-------------------------------|--|-------------------------------------|
| Decks                         | Treenails <u>Rivets</u>  | Windlass and Capstan <u>Good</u>    |
| Waterways                     | Breasthooks and Stemson  | Pumps <u>Do</u>                     |
| Comings                       | Transoms, Pointers, and Crutches   | Boats <u>Do</u>                     |
| Upper Deck Beams & Fastenings | Timbers of the Frame at the Openings   | Masts, Yards, &c. <u>Do</u>         |
| Lower Deck Beams & Fastenings | Do Do at other places  | Sails                               |
| Planksheers                   | Keelsons   | Anchors No. of <u>Good</u>          |
| Sheerstrakes                  | Clamps and Shelves   | Cables <u>and</u>                   |
| Topsides                      | Ceiling  | Hawsers and Warps <u>Sufficient</u> |
| Wales                         | Rudder   | Standing & Running Rigging          |
| Plank (Bottom) and Counter    | Copper <input checked="" type="checkbox"/> When put on <input checked="" type="checkbox"/> |                                     |

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good where examined.  
Bottom cleaned, and painted, inside cleaned, and painted  
Upper deck recaulked, Rudder bands renewed, Repairing Boilers &c.  
This vessel is now in good, and efficient condition, and in my opinion  
eligible to remain as Classed.

Committee's Minute 3<sup>rd</sup> May 1870  
 Character assigned B

J. M. Moverly  
 Survey Certificate (if required) See No. 10.6

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date \_\_\_\_\_ 18\_\_\_\_  
 on the \_\_\_\_\_ Master \_\_\_\_\_  
 Tonnage \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
 By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
 Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock \_\_\_\_\_

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classed \_\_\_\_\_

The present Condition of the

|                               |                                      |                            |
|-------------------------------|--------------------------------------|----------------------------|
| Decks                         | Treenails                            | Windlass and Capstan       |
| Waterways                     | Breasthooks and Stemson              | Pumps                      |
| Comings                       | Transoms, Pointers, and Crutches     | Boats                      |
| Upper Deck Beams & Fastenings | Timbers of the Frame at the Openings | Masts, Yards, &c.          |
| Lower Deck Beams & Fastenings | Do Do at other places                | Sails                      |
| Planksheers                   | Keelsons                             | Anchors No. of             |
| Sheerstrakes                  | Clamps and Shelves                   | Cables                     |
| Topsides                      | Ceiling                              | Hawsers and Warps          |
| Wales                         | Rudder                               | Standing & Running Rigging |
| Plank (Bottom) and Counter    | Copper _____ When put on _____       |                            |

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways \_\_\_\_\_

Committee's Minute \_\_\_\_\_ 18\_\_\_\_  
 Character assigned \_\_\_\_\_

