

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 35 Survey held at London Date March 25th 1870
 on the S. S. "Ocean King" Master Warren
 Tonnage 554 built at Sunduland When built 1863 bms.
 By whom built _____ Owners Bell & Co
 Port belonging to Sunduland Destined Voyage Coasting 25
 If Surveyed Afloat or in Dry Dock Union dry docks & Afloat

Last Survey, No. 6871 Port Iron Classed 9 A 1

REPAIRS

(t.s.b) 1.69
 The whole of the ceiling in the main hold, the timber boards and equal to three strakes in the fore hold removed for survey and the asphalt and bottom found in good order. The bottom cleaned and painted.

Present Condition of the

Decks		Freemasts		Windlass and Capstan	
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	Sufficient
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Condition, how ascertained	
Planksheers	Good	Keelsons	Good	Sails	
Sheerstrakes		Clamps and Shelves		Anchors No. of	deficient
Topsides		Ceiling		Cables	
Wales		Rudder		Hawsers and Warps	sufficient
Plank (Bottom) and Counter		Copper	When put on	Standing & Running Rigging	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good

This vessel is now in good condition and is eligible in my opinion to remain classed 9 A and be marked (t.s. 70)

Thos. W. Hawn

The Amount of Fee.....£ - : - : is received by me,

Special..... 2: 2: -

Certificate (if required) -

Committee's Minute 29 April 1870

Character assigned 9 A 1

J. Fearrick & Sons



© 2019

Lloyd's Register Foundation

IRON 446 - C145