

7926
Iron

30846

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. 624 No. 1 Survey held at London Date, first Survey 24th Feb Last Survey 26th Apr 18 70
on the Iron Ship "City of Quebec" Master D. Pebles
Tonnage 164 built at Greenwich When built 1833
By whom built _____ Owners Messrs Montgomery &
Port belonging to London Destined Voyage Quebec
If Surveyed Afloat or in Dry Dock Line Rm Dry Dock & London Dock
Last Survey, No. 6004 Port Iron Classed A.1.
(SS 103-67)-(2-68)

REPAIRS, &c.

Now done - The Windlass stripped, and new linings and Iron Whelps fitted; the Tuddler unhung, and two new plates riveted to it, one on each side; two new braces fitted, and the upper brace bushed - Two new Stanchions fitted to the fore castle on each side of English Oak, also a new piece of shelf under the fore castle beams on each side of Dantzic Oak; and four new berthing planks, on each side of Canada Elm. The bottom scraped and coated with two coats of White Zinc Paint.

Present Condition of the

Decks		Treenails	<u>none</u>	Windlass and Capstan	
Waterways	} <u>Good</u>	Breasthooks and Stenson		Pumps	} <u>Good & Sufficient</u>
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings	} <u>Good</u>	Timbers of the Frame at the openings		Masts, Yards, &c.	} <u>Good where seen</u>
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Condition, how ascertained	
Planksheers		Keelsons	} <u>Good</u>	Sails	
Sheerstrakes	} <u>Scraped & Painted</u>	Clamps and Shelves			Anchors No. of
Topsides		Rudder		Cables	
Wales		Copper	<u>none</u> When put on	Hawsers and Warps	
Plank (Bottom) and Counter	<u>Scraped & Painted</u>	Caulking of		Standing & Running Rigging	
Engine Room Skylights	<u>none</u>	Bottom, Deck, & Waterways	<u>Good</u>		
General Observations and Opinion,	Coal Bunker, Openings, Lids, &c. <u>none</u> Scuppers <u>Good</u> Cargo and Main Hatchways <u>Good</u> Hatches <u>Good</u>				

She is now in good and efficient condition, and fits in my opinion to remain classed A.1.

B. W. Raymond

The Amount of Entry Fee.....£ 2 - is received by me,

Special..... / : /

Certificate (if required) : 5 :

Committee's Minute 18th May 18 70

Character assigned A.1.

IRON 446 - 0159

record repair



© 2019

Lloyd's Register Foundation