

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No. 3153** Survey held at **Glasgow** Date **May 21st** 18**70**
 on the **Iron Ship "City of Foochow"** Master **James Watt**
 Tonnage **1034** built at **Glasgow** When built **1864**
 By whom built **Barclay** Owners **Smith & Sons**
 Port belonging to **Glasgow** Destined Voyage **Bombay**
 If Surveyed Afloat or in Dry Dock **Englis' Slip.**

Last Survey, No. **65814** Port **Iron** Classed **A. J.**
 S.S. No. **7-68** J. 68

REPAIRS

Now done, Bottom sighted, scraped and painted -

Present Condition of the

Decks	} good	Greenails	Rivets	} good	Windlass and Capstan	} good
Waterways		Breasthooks and Stemson			Pumps	
Comings		Transoms, Pointers, and Crutches			Boats	} efficient
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings			Masts, Yards, &c.	
Lower Deck Beams & Fastenings	} where	Ditto Ditto at other places		Condition, how ascertained	from the deck	
Planksheers		Keelsons	} where	Sails	} good	
Sheerstrakes		Clamps and Shells		Anchors No. of 3A-1S-2H		
Topsides		Ceiling		} seen	Cables	} efficient
Wales	Rudder	Hawsers and Warps				
Plank (Bottom) and Counter	scraped & painted	Copper Cement When put on		Standing & Running Rigging		

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. **good where seen**

She is now where seen in good and efficient condition, fit in my opinion to remain as classed

The Amount of Fee.....£ : : " is received by me, with an asterisk prefixed.

Special..... " : " : "

Certificate (if required) " : " : "

Committee's Minute **10th June** 18**70**

Character assigned



© 2019

Lloyd's Register Foundation

IRON 446-0154