

ANNUAL SURVEYS.

No. 199 Survey held at London Date 18 June 1870
 on the iron ship "Thomas Bell" Master H. R. Williamson
 Tonnage 138 Built at P. Glasgow When built 1862-9 mo
 By whom built Reid Owners S. Bell
 Port belonging to Birkenhead Destined Voyage Shanghai
 If Surveyed Afloat or in Dry Dock Canal Dry Dock

Last Survey, No. 6998 Port of Iron Classed SAI
15.5 Apr. 68 4.69

The present Condition of the

Decks	Ironails <u>Rivets</u>	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>put</u> When put on <u>part 1862 1868</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where examined

Bottom cleaned and coated with patent Composition.
Is now in good and efficient condition, and in my
opinion eligible to remain as classed.

Committee's Minute 21st June 1870

Character assigned A 1

H. H. Warner

Certificate (if required)

No. 371 Survey held at London Date 17 June 1870
 on the iron ship "Herculan" Master
 Tonnage 1042 Built at Switzerland When built 1863-5 mo
 By whom built Pile Owners G. D. Sykes
 Port belonging to London Destined Voyage India
 If Surveyed Afloat or in Dry Dock Canal Dry Dock and afloat

Last Survey, No. 7244 Port of Iron Classed SAI
15.5 Apr. 68 5.69

The present Condition of the

Decks	Ironails <u>Rivets</u>	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper When put on	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where examined

Parts of bottom plating overhauled and caulked. Bottom cleaned
and coated with Paint and Sallow. Is now in good and ef-
icient condition and in my opinion
eligible to remain as classed. SAI.

Committee's Minute 21st June 1870

Character assigned A 1

H. H. Warner Certificate (if required).