

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. 105 No. 22370 Survey held at Birkenhead Date, first Survey 24 June Last Survey 27 June 1870

on the Iron Steamer "Hartlepool" Master Butchart

Tonnage 557 built at Sunderland When built 1865-10 mo

By whom built Laird Owners E. Gourley

Port belonging to Sunderland Destined Voyage Azure

If Surveyed Afloat or in Dry Dock Clayton's dry dock & afloat

Last Survey, No. 6721 Port Iron Classed A

REPAIRS, &c. 155821 67/68

Fore side of Water ballast tank. Three strakes of ceiling on each side removed in flat & one strake at the bilge. Iron holes of water ballast tank taken off and the vessel where seen good. Cement repaired where required. one Beam knee riveted in fore compartment.

Present Condition of the

Decks	} Good	Freemails	Reeds	Good	Windlass and Capstan
Waterways		Breasthooks and Stemson			Pumps
Comings		Transoms, Pointers, and Crutches			Boats
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings	where		Masts, Yards, &c.
Lower Deck Beams & Fastenings		Ditto Ditto at other places			Condition, how ascertained
Planksheers		Keelsons	seen		Sails
Sheerstrakes		Clamps and Shells			Anchors No. of
Topsides	} seen	Ceiling			Cables
Wales		Rudder			Hawsers and Warps
Plank (Bottom) and Counter		Copper Cement	When put on	1665/66	Standing & Running Rigging
Engine Room Skylights	Good	Caulking of			
Coal Bunker, Openings, Lids, &c.	Good	Bottom, Deck, & Waterways	Good		
Scuppers	Good	Cargo and Main Hatchways	Good		
Hatches	Good				

General Observations and Opinion, She is now in good condition and in my opinion may continue as classed A and marked S.S. No 2-70 -

Wm. C. D. Dore

The Amount of Entry Fee.....£ - : - is received by me,

July 1870 Special.....2 : 2 : - 1/7/70 R.M.S.
Certificate (if required) - : -

Committee's Minute Liverpool, 5th July 1870

Character assigned A - 155821 67/68



© 2019

Lloyd's Register
Foundation

"Hartlepool"
- 22.3.73 -



© 2019

Lloyd's Register
Foundation