

8252

REPORT of SURVEY for REPAIRS.

Rec 9/9/70

Supplement No. 5827 Survey held at Glasgow Date, first Survey 22nd July Last Survey 25th July 1870
No. in Reg. Book. 9 on the Iron Screw Steamer "Renfrewshire" Master Watt
Tonnage 773 ^{gross} 511 ^{register} built at Port Glasgow When built 1870 6th months
By whom built Blackwood & Gordon Owners James Turnbull
Port belonging to Port Glasgow Destined Voyage Clyde to Black Sea
If Surveyed Afloat or in Dry Dock On Patent Slip

Last Survey, No. 5816 8182 Port Port Glasgow Iron. Classed 90 A1

REPAIRS, &c. of damage occasioned by vessel having gone on shore on the Island of Arran while upon her trial trip.

Vessel placed on Patent Slip. Four plates of bottom on Port side, and one on Starboard side removed and renewed; three frames and reverse frames, three floors and bilge keelson in way of same repaired, and all rivets in plating, frames, &c. in way of damage renewed, including Cement and Hold ceiling.

Present Condition of the

Decks	Where seen Good	Freemails	Rivets	Where seen Good	Windlass and Capstan	Good
Waterways	do do	Breasthooks and Stemson		do do	Pumps	do
Comings	do do	Transoms, Pointers, and Crutches		do do	Boats	do
Upper Deck Beams & Fastenings	do firm	Timbers of the Frames at the openings		do do	Masts, Yards, &c.	do
Lower Deck Beams & Fastenings	do firm	Ditto Ditto at other places		do do	Condition, how ascertained	By observation
Planksheers	Where seen Good	Keelsons		do do	Sails	Well found
Sheerstrakes	Plating do do	Clamps and Shelves		do do	Anchors	No. of 3 Bowers 1 Stream 2 Kedge
Topsides	do do do	Ceiling		do do	Cables	Complete
Wales	do do do	Rudder		do do	Hawsers and Warps	Sufficient
Plank (Bottom) and Counter	Plating do do do	Copper	When put on Coated 1870		Standing & Running Rigging	Good
Engine Room Skylights	Good	Caulking of				
Coal Bunker, Openings, Lids, &c.	Good	Bottom, Deck, & Waterways	Good when examined			
Scuppers	Good					
Cargo and Main Hatchways	Good					
Hatches	Good					

General Observations and Opinion,

She is now in good and efficient condition, and eligible to remain as classed.

The Amount of Entry Fee.....£ 2 : " : " is received by me,

Special..... " : " : "

Certificate (if required) " : " : "

Committee's Minute 9th September 1870

Character assigned 90 A1 Now A1 Spar deck

renew damage repair

* Vica Gen. Com. Min.

13th Oct 1870

£778 00 lds.

Saml. Laphorn

© 2019 Lloyd's Register Foundation