

8479
Damage Survey

REPORT of SURVEY for REPAIRS.

Rec 28/11/70

No. in Reg. Book. **No. 11292** Survey held at Shields Date, first Survey 26th Oct^r Last Survey 2nd November 1870
on the Iron Steamship "Hilda" Master W. Sanderson
Tonnage 650 built at Port Glasgow When built 1865, 5 mo.
By whom built Reid Owners Cytheren Mining Co (Linn)
Port belonging to London Destined Voyage Norway
If Surveyed Afloat or in Dry Dock Afloat and on a "Beach"

Last Survey, No. 7598 Port Grove Classed B. 1.
11-69 18.5.2-69 11-69

REPAIRS, &c.

Now done in consequence of damage through collision.
On the Port bow:- four outside plates renewed; one broken frame efficiently scarphed; one length of main deck stringer plate renewed; two bent frames reset; the fore length of waterway renewed; the Hawse-pipe refitted and bolted; and the tween deck ceiling in the way of the damage renewed.
The bottoms now scraped and painted.

Present Condition of the

Decks	Freemasts	Reinforced	Windlass and Capstan
Waterways	Good	Good	Pumps
Transoms	"	"	Boats
Deck Beams & Fastenings	"	"	Masts, Yards, &c.
Deck Beams & Fastenings	"	"	Condition, how ascertained
Keelsons	"	"	Sails
Clamps and Shelves	"	"	Anchors No. of
Ceiling	"	"	Cables
Rudder	"	"	Hawsers and Warps
Copper Cement When put on	1867	"	Standing & Running Rigging
Caulking of	"	"	
Bottom, Deck, & Waterways	Good	"	
Room Skylights	Good	"	
Coal Bunker, Openings, Lids, &c.	Good	"	
Scuppers	Good	"	
Cargo and Main Hatchways	Good	"	
Hatches	Good	"	

Observations and Opinion,

She is in good and efficient condition, and
my opinion, eligible to remain as classed viz. B. 1.

J. J. Bone

The Amount of Entry Fee.....£ 2: " : is received by me,

Damage Survey Special..... 2: 2: "

Certificate (if required) " : " : "

Committee's Minute 29th November 1870

Character assigned B. 1.

record damage repairs

W. H.



© 2019

Lloyd's Register Foundation

IRON 447-0285