

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No. 25398** Survey held at Birkenhead Date Aug. 3 to 6 18 68
 on the (S.M.) S.S. "Gambia" Master _____
 Tonnage 1167 Built at Newcastle When built 1860 - 3 ms
 By whom built Leslie Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Great Floak graving dock

Last Survey, No. _____ Port _____ Classed A3
 (S.P. No. 2-65)

REPAIRS now done through damage

Two plates taken off, straightened & rivetted, & one plate renewed in place of bottom on Starboard side; also four plates on each side of the fore foot taken off, straightened & rivetted - the lower part of them also straightened, & the bottom coated with Composition.

Not now found in the dock
J.F.Z.
2/2/77

Present Condition of the

Decks <u>Good</u>	Tacomaile <u>Good</u>	Windlass and Capstan <u>Good & sufficient</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame at the openings <u>"</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Ditto Ditto at other places <u>"</u>	Condition, how ascertained <u>Seen from deck</u>
Planksheers <u>"</u>	Keelsons <u>"</u>	Sails <u>Good & sufficient</u>
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	Anchors No. of <u>"</u>
Topsides <u>"</u>	Ceiling <u>"</u>	Cables <u>"</u>
Wales <u>"</u>	Rudder <u>"</u>	Hawsers and Warps <u>"</u>
<u>Plates</u> Plank (Bottom) and Counter <u>"</u>	Cement <u>Good</u> When put on <u>1865</u> Copper <u>where seen</u>	Standing & Running Rigging <u>"</u>

General Observations and Opinion, Caulking of Bottom, Deck, & Waterways. Satisfactory

Is now in an efficient condition & in my opinion eligible to remain as Classed.

The Amount of Fee.....£ : : is received by me,
 Special..... / : / : "

Certificate (if required) _____

Committee's Minute Liverpool Feb. 2 - 1877

Character assigned Record only.

Fees not paid transmit Report to London.
M. H. 16



© 2019

Lloyd's Register
 Foundation

IRON448-0028