

8730
ANNUAL SURVEYS.

No. 22665 Survey held at Liverpool Date Feb 7th 1871
 on the S. Ship Baroda Master J. Gulley
 Tonnage 1364 Built at Belfast When built 1864-4 Dec
 By whom built Harland Owners Brocklebank
 Port belonging to Liverpool Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Herculeanum Dry Dock

Last Survey, No. 7321 Port of Iron Classed * A 1
 (S.S. No. 68) 69

The present Condition of the

Decks	<u>Good</u>	Rivets	<u>When seen good</u>	Windlass and Capstan	<u>Good</u>
Waterways	"	Treenails	"	Pumps	"
Comings	"	Breasthooks and Stemson	"	Boats	<u>Four</u>
Upper Deck Beams & Fastenings	"	Transoms, Pointers, and Crutches	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Fibers of the Frame at the Openings	"	Sails	"
Planksheers	"	Ditto ditto at other places	"	Anchors	No. of <u>3 B. 1 S. 2 H.</u>
Sheerstrakes	"	Keelsons	"	Cables	<u>Good</u>
Topsides	"	Clamps and Shelves	"	Hawsers and Warps	<u>And</u>
Wales	"	Ceiling	"	Standing & Running Rigging	<u>Sufficient</u>
Plank (Bottom) and Counter	"	Rudder	"		
		Copper	<u>Cement</u> When put on <u>1864</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good

The Bottom cleaned and coated with Dr. James' Composition. She is now when seen in good condition, and in my opinion eligible to remain as classed.

Committee's Minute Liverpool 7th February 1871

Character assigned * A 1

Certificate (if required)

No. 5622 Survey held at Liverpool Date Feb 7th 1871
 on the S. Ship Thandeish Master J. Tennett
 Tonnage 1004 Built at Port Glasgow When built 1864-10 Dec
 By whom built Duncan Owners Nicholson &
 Port belonging to Liverpool Destined Voyage Melbourne
 If Surveyed Afloat or in Dry Dock Brunswick Dry Dock

Last Survey, No. 5622 Port of Iron Classed * A 1
 (S.S. No. 68) 68

The present Condition of the

Decks	<u>Good</u>	Rivets	<u>When seen good</u>	Windlass and Capstan	<u>Good</u>
Waterways	"	Treenails	"	Pumps	"
Comings	"	Breasthooks and Stemson	"	Boats	<u>Five</u>
Upper Deck Beams & Fastenings	"	Transoms, Pointers, and Crutches	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Fibers of the Frame at the Openings	"	Sails	"
Planksheers	"	Ditto ditto at other places	"	Anchors	No. of <u>3 B. 1 S. 2 H.</u>
Sheerstrakes	"	Keelsons	"	Cables	<u>Good</u>
Topsides	"	Clamps and Shelves	"	Hawsers and Warps	<u>And</u>
Wales	"	Ceiling	"	Standing & Running Rigging	<u>Sufficient</u>
Plank (Bottom) and Counter	"	Rudder	"		
		Copper	<u>Cement</u> When put on <u>1864</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good

The Bottom cleaned and painted with two coats of paint and one coat of tallow. She is now in good condition and in my opinion eligible to remain as classed.

Committee's Minute Liverpool 7th February 1871

Character assigned * A 1

Certificate (if required)

"Baroda"
22.665
"Khanderish"



© 2019

Lloyd's Register
Foundation