

# ANNUAL SURVEYS.

No. 160 Survey held at London Date 18 Feb 71 18 71  
 on the Iron Ship "Orizaba" Master A. Rice 2d Rumb  
 Tonnage 226 Built at Pallion When built 1860-9 mo  
 By whom built A. G. G. G. Owners Harbore etc  
 Port belonging to Liverpool Destined Voyage Antigua  
 If Surveyed Afloat or in Dry Dock Linthouse Dry Dock

Last Survey, No. 8102 Port of Ron Classed SAI  
 (5-5-68) 7-70

The present Condition of the

|                               |                                      |                            |
|-------------------------------|--------------------------------------|----------------------------|
| Decks                         | Treacils <u>Rivets</u>               | Windlass and Capstan       |
| Waterways                     | Breasthooks and Stems                | Pumps                      |
| Comings                       | Transoms, Pointers, and Crutches     | Boats                      |
| Upper Deck Beams & Fastenings | Timbers of the Frame at the Openings | Masts, Yards, &c.          |
| Lower Deck Beams & Fastenings | Ditto ditto at other places          | Sails                      |
| Planksheers                   | Keelsons                             | Anchors No. of             |
| Sheerstrakes                  | Clamps and Shells                    | Cables                     |
| Topsides                      | Ceiling                              | Hawsers and Warps          |
| Wales                         | Rudder                               | Standing & Running Rigging |
| Plank (Bottom) and Counter    | Copper                               |                            |

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good where Examined  
Bottom cleaned and painted  
Is now in good and efficient condition  
and in my opinion eligible to remain as classed.  
 Committee's Minute 28<sup>th</sup> February 1871  
 Character assigned SAI  
 Certificate (if required).

No. 290 Survey held at London Date 23 Feb 71 18 71  
 on the Iron Bark "John Bull" Master J. Harries  
 Tonnage 484 Built at Sunderland When built 1860-2 mo  
 By whom built A. G. G. G. Owners Temperleys  
 Port belonging to London Destined Voyage Montreal  
 If Surveyed Afloat or in Dry Dock Linthouse Dry Dock

Last Survey, No. 7695 Port of Ron Classed SAI  
 (5-5-68) 2-70

The present Condition of the

|                               |                                      |                            |
|-------------------------------|--------------------------------------|----------------------------|
| Decks                         | Treacils <u>Rivets</u>               | Windlass and Capstan       |
| Waterways                     | Breasthooks and Stems                | Pumps                      |
| Comings                       | Transoms, Pointers, and Crutches     | Boats                      |
| Upper Deck Beams & Fastenings | Timbers of the Frame at the Openings | Masts, Yards, &c.          |
| Lower Deck Beams & Fastenings | Ditto ditto at other places          | Sails                      |
| Planksheers                   | Keelsons                             | Anchors No. of             |
| Sheerstrakes                  | Clamps and Shells                    | Cables                     |
| Topsides                      | Ceiling                              | Hawsers and Warps          |
| Wales                         | Rudder                               | Standing & Running Rigging |
| Plank (Bottom) and Counter    | Copper <u>10 in</u>                  |                            |

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good where Examined  
Bottom cleaned and coated with coal tar.  
Is now in good and efficient condition  
and in my opinion eligible to remain as  
 Committee's Minute 28<sup>th</sup> February 1871 Classed  
 Character assigned SAI  
 Certificate (if required).