

Iron. 8803
Change of Name and Owners.

REPORT of SURVEY for REPAIRS.

Delayed in order to get particulars of change of owners

No. in Reg. Book.

No.

Survey held at

London

Date, first Survey

17th Oct^r

Last Survey

1870

on the *British Commodore* late Master *Quine*

Tonnage *1405* built at *Newcastle*

When built *1868*

By whom built *Palmer*

Owners *British Ship Owners Co.*

Port belonging to *Liverpool*

Destined Voyage *Cardiff then Bombay*

If Surveyed Afloat or in Dry Dock *Reed's Dry Dock*

Last Survey, No.

7566

Port

Iron

Classed

**A1.*

12,69.

REPAIRS, &c.

*Outside cleaned and painted, and bottom
tallowed.*

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

General Observations and Opinion,

Treenails / Rivets

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the openings

Ditto Ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper Cemented When put on

Caulking of

Bottom, Deck, & Waterways

Coal Bunker, Openings, Lids, &c.

Scuppers

Cargo and Main Hatchways

Hatches

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

Good

where

seen.

Good

where

seen.

168.

Good and

Complete

where seen.

*Is in good and efficient condition, and fit
in our opinion to remain as classed - *A1.*

J. H. Eastlake.

The Amount of Entry Fee.....£ / : - : -

Special..... - : - : -

Certificate (if required) : 5 : -

Committee's Minute

14th March

18

Character assigned

**A1*



© 2019

Lloyd's Register
Foundation

IRON 1448-0154