

ANNUAL SURVEYS.

8850

57492

No. 675 Survey held at London Date 22nd Feb^y 18 71
 on the iron ship "Grady Mair" Master J. Potter
 Tonnage 837 Built at Greenock When built 1868-10 mo
 By whom built Steele Owners Thompson & Co
 Port belonging to Leith Destined Voyage Shanghai via Cardiff
 If Surveyed Afloat or in Dry Dock Union dry dock

Record 11

Last Survey, No. 7893 Port of Gron. Classed SAI
4.70

The present Condition of the

Decks	Treenails <u>Rivets</u>	Windlass and Capstan
Waterways	Breasthooks and Stenson	Pumps
Comings	Transoms Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>Iron</u> When put on <u>1868</u>	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good where Examined
Bottom cleaned and coated with Paint and Gallon.
Is now in good, and efficient condition, and
in my opinion eligible to remain as classed.

Committee's Minute 24th March 18 71
 Character assigned * A 1
M. H. Burnes
 Certificate (if required).

No. 280 Survey held at London Date 17th March 18 71
 on the iron ship "Sea Queen" Master J. Cunningham
 Tonnage 873 Built at Glasgow When built 1858
 By whom built Stephen Owners J. Allan & Sons
 Port belonging to London Destined Voyage India
 If Surveyed Afloat or in Dry Dock Leicestershire Dry Dock

Last Survey, No. 7882 Port of Gron. Classed SAI
(5.5 103-69) 4.70

The present Condition of the

Deck	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stenson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>Iron</u> When put on <u>1869</u>	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good where Examined
Bottom cleaned and painted
Is now in good, and efficient condition, and
in my opinion eligible to remain as classed.

Committee's Minute 24th March 18 71
 Character assigned * A 1
M. H. Burnes
 Certificate (if required).

IRON 448-0202