

# ANNUAL SURVEYS.

Rec 20/3/71

No. 1200 Survey held at London Date 28<sup>th</sup> Feb March 2<sup>nd</sup> 1871  
 on the Iron Ship The Bruce Master And<sup>r</sup> Braes  
 Tonnage 1200 Built at Glasgow When built 1866 <sup>10<sup>th</sup> mth</sup>  
 By whom built Aiskin Owners W. & R. Wright  
 Port belonging to Liverpool Destined Voyage Cardiff  
 If Surveyed Afloat or in Dry Dock Greens Lower Dock Victoria Dock

Last Survey, No. 8023 Port of London Classed A. 1.  
See annexed Report. 5/0

The present Condition of the

Decks <u>good</u>	Treenails <u>Rivets where seen good</u>	Windlass and Capstan <u>in good order</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame at the Openings <u>"</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Ditto ditto at other places <u>"</u>	Sails <u>"</u>
Planksheers <u>"</u>	Keelsons <u>"</u>	Anchors No. of <u>3 &amp; 1 S. 2 10</u>
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	Cables <u>"</u>
Topsides <u>"</u>	Ceiling <u>"</u>	Hawsers and Warps <u>"</u>
Wales <u>"</u>	Rudder <u>efficient</u>	Standing & Running Rigging <u>"</u>
Plank (Bottom) and Counter <u>"</u>	Copper <u>When put on</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Good

Survey'd in Ballast. As far as seen, she is in good condition  
Cleaned and Coated her outside. — The next survey being due. I left notice  
respecting the same at the above date with the Master, who informed me, he had  
forwarded the same to the Owners. — I believe that for the present they have declined  
 Committee's Minute 14<sup>th</sup> March 1871 the Survey; and that the ship has left this Port.

Character assigned

Samuel Presious

Certificate (if required)

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date \_\_\_\_\_  
 on the \_\_\_\_\_ Master \_\_\_\_\_  
 Tonnage \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
 By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
 Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock \_\_\_\_\_

deferred  
18  
15/3/71  
17. 3. 71

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classed \_\_\_\_\_

The present Condition of the

Decks _____	Treenails _____	Windlass and Capstan _____
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame at the Openings _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Ditto ditto at other places _____	Sails _____
Planksheers _____	Keelsons _____	Anchors No. of _____
Sheerstrakes _____	Clamps and Shelves _____	Cables _____
Topsides _____	Ceiling _____	Hawsers and Warps _____
Wales _____	Rudder _____	Standing & Running Rigging _____
Plank (Bottom) and Counter _____	Copper _____ When put on _____	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Committee's Minute \_\_\_\_\_ 18

Character assigned \_\_\_\_\_

Certificate (if required).

IRON 448 - 0260



© 2019

Lloyd's Register

Foundation



Page  
of the Bruce



© 2019

Lloyd's Register  
Foundation