

REPORT of SURVEY for REPAIRS.

9022

\$357

No. in Reg. Book. 84 No. 1198 Survey held at London Date, first Survey 17th Apr 18th Last Survey April 22^d 1871
 on the Iron Ship Hannibal Master G. E. Dunn
 Tonnage 1198 built at Glasgow When built 1862
 By whom built Smith Owners W. Dixon
 Port belonging to Liverpool Destined Voyage Alex (via Cardiff)
 If Surveyed Afloat or in Dry Dock Wigram's dry dock, & Victoria docks afloat
 Last Survey, No. 7855 Port Home Classed A. 1. S. S. no 1-66
12.66

REPAIRS, &c.

Clean'd the Outside, examin'd, and recoated it. -
 I was at the ship on Saty, and it was reported to me, she would leave on
 that day for Cardiff. - S. P.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper When put on	Standing & Running Rigging
Engine Room Skylights	Caulking of	
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways	
General Observations and Opinion,	Scuppers	Cargo and Main Hatchways
		Hatches


The Amount of Entry Fee.....£ : : is received by me,

Special..... : :

Certificate (if required) : :

Committee's Minute 25th April 18 71

Character assigned



IRON488-0372