

Iron 9437 31922

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. 146 No. 146 Survey held at London Date, first Survey Aug 17th Last Survey Sept 18th 1871
on the S. 'White Eagle' (Gen) Master W. Andrews
Tonnage 278 built at Glasgow When built 1855
By whom built _____ Owners Bille
Port belonging to London Destined Voyage Adelaide
If Surveyed Afloat or in Dry Dock Commercial dry dock & W. S. Dock
Last Survey, No. 0287 Port Iron. Classed * A 1
REPAIRS, &c. (S. S. No 1. 68.) 9.70

This vessel while being docked (to paint) slipped between two tiers of blocks; on being again floated and placed on proper blocks, the only damage found was the plates in two places slightly indented and two butts strained, the ceiling being lifted over these parts it was found that all was as sound as before, to be certain of which the cement was cut out in way of the same and renewed.

The vessels bottom which had been coated with soap was very clean and has now had two coats of zinc paint and one of soap.

Present Condition of the

Decks	} Good	Transoms	} Good	Windlass and Capstan	} Good & sufficient
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Condition, how ascertained	
Planksheers		Keelsons		Sails	
Sheerstrakes		Clamps and Shelves		Anchors No. of	
Topsides		Ceiling		Cables	
Wales		Rudder		Hawsers and Warps	
Plank (Bottom) and Counter		Gropen Caulking of		Standing & Running Rigging	
Engine Room Skylights	Coal Bunker, Openings, Lids, &c.	Scuppers	Cargo and Main Hatchways	Hatches	good

General Observations and Opinion,

This vessel is eligible in my opinion to remain as classed * A 1

The Amount of Entry Fee.....£ - : - : is received by me,

Special..... 1 : 1 : 10/10

Certificate (if required)..... : : : 10/10

Committee's Minute 10th October 71 1871

Character assigned * A 1



© 2019

Lloyd's Register Foundation