

ANNUAL SURVEYS.

No. 23074 Survey held at Birkenhead Date Sept 25-20 1871
 on the Iron S "Antim" Master C. Neil
 Tonnage 993 Built at Pallion When built 1864-3ms
 By whom built Doyford Owners P. Carvell
 Port belonging to Lpool Destined Voyage India
 If Surveyed Afloat or in Dry Dock Afloat & in Mues Clayton's graving dock

Last Survey, No. 8470 Port of Iron Classed * - A - 1 - 10-70
 (S.P. No. 1-69) 70

The present Condition of the

Decks	Treenails <u>Rivets</u>	Windlass and Capstan	} <u>Good</u>
Waterways	Breasthooks and Stemson	Pumps	
Comings	Transoms, Pointers, and Crutches	Boats	} <u>L</u>
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.	
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails	} <u>efficient</u>
Planksheers	Keelsons	Anchors, No. of	
Sheerstrakes	Clamps and Shelves	Cables	} <u>where</u>
Topsides	Ceiling	Hawsers and Warps	
Wales	Rudder	Standing and Running Rigging	<u>Seen</u>
Plates (Bottom) and Counter	Copper	When put on	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Satisfactory

The bottom scraped & coated with red lead & tallow. Appears
 now in good condition & in my opinion eligible to remain
 as Classed -
 Committee's Minute Liverpool, 31st October, 1871

Character assigned * A 1

J. G. E.

Certificate (if required).

No. 372 Survey held at Birkenhead Date Oct 13-23 1871
 on the Iron S "Princ Oscar" Master J. Fowler
 Tonnage 1292 Built at W. J. Pl When built 1864-10 ms
 By whom built Pile Owners S. Graves
 Port belonging to Lpool Destined Voyage India
 If Surveyed Afloat or in Dry Dock Afloat & in Great Horse graving dock

Last Survey, No. 8505 Port of Iron Classed * - A - 2 - 12-70
 (S.P. No. 1-68) 7

The present Condition of the

Decks	Treenails <u>Rivets</u>	Windlass and Capstan	} <u>Good</u>
Waterways	Breasthooks and Stemson	Pumps	
Comings	Transoms, Pointers, and Crutches	Boats	} <u>L</u>
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.	
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails	} <u>efficient</u>
Planksheers	Keelsons	Anchors, No. of	
Sheerstrakes	Clamps and Shelves	Cables	} <u>where</u>
Topsides	Ceiling	Hawsers and Warps	
Wales	Rudder	Standing and Running Rigging	<u>Seen</u>
Plates (Bottom) and Counter	Copper <u>Cem</u>	When put on <u>64</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Satisfactory

The bottom scraped & coated with red lead & tallow. Is
 now in good condition & in my opinion eligible to remain
 as Classed -
 Committee's Minute Liverpool, 31st October, 1871

Character assigned * A 1

J. G. E.

Certificate (if required).

Antrim

Prince Oscar

23014



© 2019

Lloyd's Register
Foundation