

# REPORT of SURVEY for REPAIRS.

No. in Reg. Book. *Supp 1* No. *9510* Survey held at *London* Date, first Survey *Nov 1<sup>st</sup>* Last Survey *Nov 2<sup>nd</sup> 1871*  
 on the *S. S. "Eastella" (Iron)* Master *Neubauer*  
 Tonnage *274* built at *Sunderland* When built *1871 4 mo*  
 By whom built \_\_\_\_\_ Owners *Jackson & Co*  
 Port belonging to *Hull* Destined Voyage *Madaira*  
 If Surveyed Afloat or in Dry Dock *Millwall docks dry dock*  
 Last Survey, No. *9044* Port *Iron* Classed *90 A 1*  
*8-71*

## REPAIRS, &c.

*In consequence of damage See special report.*  
*a few butts and seams in bottom recaulked,*  
*the bottom repainted, and propeller renewed.*

### Present Condition of the

Decks	} <i>Good</i>	Greenails	} <i>Good</i>	Windlass and Capstan	} <i>Sufficient</i>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Condition, how ascertained	
Planksheers		Keelsons		Sails	
Sheerstrakes		Clamps and Shelves		Anchors No. of	
Topsides		Ceiling		Cables	
Wales		Rudder		Hawsers and Warps	
Plank (Bottom) and Counter		Copper		Standing & Running Rigging	
Engine Room Skylights	Caulking of	Cargo and Main Hatchways	Hatches <i>good</i>		
General Observations and Opinion,	Bottom, Deck, & Waterways <i>good</i>	Scuppers			

*This vessel is eligible in my opinion to*  
*remain as classed 90 A 1*

The Amount of Entry Fee.....£ : : is received by me, *Thos. W. Wawn*

Special..... — : — : —

Certificate (if required) : :

Committee's Minute *14<sup>th</sup> November 1871*

Character assigned *90 A 1*

*Damage £ 3.3.0 ago.*  
*13.11.71*