

# REPORT of SURVEY for REPAIRS.

*Change of Owners - 3/10/98*

No. in Reg. Book. 612 No. 956 Survey held at London Date, first Survey 22 Nov 1871  
 on the iron ship "Enterprise" Master Phillips  
 Tonnage 147 built at Ramsay When built 1863 11 mo  
 By whom built Litson Owners Shan Saville & Co  
 Port belonging to London Destined Voyage Australia  
 If Surveyed Afloat or in Dry Dock Reft. Green's dry dock and afloat  
 Last Survey, No. 8414 Port Iron Classed Lat 1 S.S. No. 67  
11-70

REPAIRS, &c.

The timber-boards and ceiling equal to three strakes fore and aft on each side removed.

Mid-lars unhung, wood linings stripped, and the chain-cables ranged on deck for Examination.

Plating and Frames in tween decks, as also upper-deck beams, stinger and tie-plates together with the parts where exposed by the removal of the ceiling have been cleaned and painted. Bottom coated with Paint and Gallon.

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

Coal Bunker, Openings, Lids, &c.

Scuppers

Cargo and Main Hatchways

Hatches

General Observations and Opinion,

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the openings

Ditto Ditto at other places

Keelsons

Clamps and Shells

Ceiling

Rudder

Copper

Caulking of

Bottom, Deck, & Waterways

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

*Is now in good, and efficient condition and in my opinion eligible to remain as classed and to be marked (S.S. No. 71)*

The Amount of Entry Fee.....£ 1 : - : - is received by me,

Special.....4 : 4 : -

Certificate (if required) : 5 :

Committee's Minute 24<sup>th</sup> November 1871

Character assigned

S. S. No. 2-71



© 2019

Lloyd's Register Foundation

100N450-0018