

9708  
Damage and S.S. No 1

32053

# REPORT of SURVEY for REPAIRS.

No. in Reg. Book. 530 No. 1 Survey held at London Date, first Survey Dec 23/71 Last Survey Jan 4<sup>th</sup> 1872  
 on the S.S. "Souvenir" Iron Master E. French  
 Tonnage 219 built at Port Glasgow When built 1866 4 mo  
 By whom built \_\_\_\_\_ Owners Sydney & Co  
 Port belonging to London Destined Voyage France or Belgium  
 If Surveyed Afloat or in Dry Dock Carters dry dock Millwall  
 Last Survey, No. 4751 Port Iron. Classed ~~A~~ B 5, 66

REPAIRS, &c. In consequence of damage, see Special Report —  
 Stem taken out and set in form again. Three plates on each bow also a garboard plate on each side refitted, several butts recaulked and rivets renewed. Ceiling lifted, <sup>9 strakes on each side</sup> to remove started rivets (more than equal to S.S. No 1) and both surfaces of the plating exposed) —  
 One plate on Starboard side refitted and one on port heated and set in form — Deck caulked where required —

Present Condition of the

Decks		Treenails		Windlass and Capstan	
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Condition, how ascertained	<u>Good &amp;</u>
Planksheers	<u>Good</u>	Keelsons	<u>Good</u>	Sails	<u>sufficient</u>
Sheerstrakes		Clamps and Shelves		Anchors No. of	
Topsides		Ceiling		Cables	
Wales		Rudder		Hawsers and Warps	
Plank (Bottom) and Counter		Copper When put on		Standing & Running Rigging	
Engine Room Skylights		Caulking of			
General Observations and Opinion,		Bottom, Deck, & Waterways		Cargo and Main Hatchways	<u>Hatches good</u>
		Coal Bunker, Openings, Lids, &c.			
		Scuppers			

This vessel is eligible in my opinion to remain as  
 classed B  
 and marked S.S. No 1. 72

The Amount of Entry Fee.....£ 10 is received by me,  
 Special..... 1  
 Certificate (if required) : 5

Committee's Minute 12<sup>th</sup> January 1872

Character assigned B 1 S.S. No 1-72

Special Damage 2.2.



© 2019

Lloyd's Register  
 Marine Surveyors  
 Foundation