

REPORT of SURVEY for REPAIRS.

Rec 4/4/92

No. in Reg. Book. **No. 10310** Survey held at Sunderland Date, first Survey 4th March Last Survey 7th March 1892
 on the Iron. Ssr. "Celsus" Master J Haig
 Tonnage 1007 built at Sunderland When built 1871 (9 mo)
 By whom built Thompson Owners Gulliford and Co
 Port belonging to Sunderland Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Austin's Dry Dock
 Last Survey, No. 10310/9579 Port Sunderland Classed 90.A.1.
 REPAIRS, &c. None done.

The pen of the Anchor being driven through the
 Bow plating, introduced a patch, with a "liner" inside;
 Repaired the Frame with an additional angle bar;
 Examined the Cement, &c, in the Tanks and Engine Room,
 Some minor repairs were made to the Engine; the
 Bottom sighted; cleaned; a few Butts recaulked
 in the flat in way of Engine; and Bottom payed
 with Composition paint.

Present Condition of the

Decks	Good where seen	Breasthooks and Stemson Transoms, Pointers, and Crutches Timbers of the Frame at the openings Ditto Ditto at other places Keelsons Clamps and Shelves Ceiling Rudder Copper paint When put on Caulking of Bottom, Deck, & Waterways	Good where seen none	Windlass and Capstan Pumps Boats Masts, Yards, &c. <u>good</u> Condition, how ascertained <u>insp</u> Sails Anchors No. of <u>3 B. 15. 2 K</u> Cables Hawser and Warps Standing & Running Rigging	Good and sufficient where seen				
Waterways									
Comings									
Upper Deck Beams & Fastenings									
Lower Deck Beams & Fastenings									
Planksheers									
Sheerstrakes									
Topsides									
Wales									
Plank (Bottom) and Counter									
Engine Room Skylights	<u>good</u>	Coal Bunker, Openings, Lids, &c.	<u>good</u>	Scuppers	<u>good</u>	Cargo and Main Hatchways	<u>good</u>	Hatches	<u>good</u>

General Observations and Opinion,

She is now in good and efficient Condition and
 fit in my opinion to remain as Classed Viz 90.A.1.
Joseph Keen,

The Amount of Entry Fee.....£ " : " : " is received by me,

Special..... " : " : " : "

Certificate (if required) " : " : "

Committee's Minute 5th April 18 92

Character assigned 90 A 1



© 2019

Lloyd's Register
Foundation