

REPORT OF SURVEY for REPAIRS.

No. in Reg. Book. 6 No. 1056 Survey held at London Date, first Survey 21st Sept. Last Survey 9th Dec. 1872
on the iron screw steamer "Dacia" Master William
Tonnage 1626 built at Sunderland When built 1867-11 mo
By whom built Laing Owners India Rubber Company
Port belonging to London Destined Voyage not fixed
If Surveyed Afloat or in Dry Dock on the Victoria Dock Pontoon and afloat
Last Survey, No. 8013 Port Iron Classed F B / 1

REPAIRS, &c.

270

The timber-boards and ceiling equal to one strike fore and aft on each side removed, the frames plating rivets &c in way of same found to be in good condition, the cement coating found and good and adhering satisfactorily to the iron.

Rudder, pintles repaired, lowerhold scraped and painted throughout. bottom cleaned, and coated with Paint and Gallon. fore topmast bent of Pine.

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

General Observations and Opinion,

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the openings

Ditto Ditto at other places

Keelsons

Clamps and Shells

Ceiling

Rudder

Copper

Caulking of

Bottom, Deck, & Waterways

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

Cargo and Main Hatchways

Hatches

The Amount of Entry Fee.....£ - : - : is received by me,

Special.....3 : 3 :

Certificate (if required) : 5 :

Committee's Minute 29th October 1872

Character assigned

B

S. S. No 1-72

TPW



© 2019

Lloyd's Register Foundation

1200452-0332