

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. 116 No. 3574 Survey held at Glasgow Date, first Survey 21st Oct Last Survey 1st Nov 18 72
on the S.S. "Kinsale" Master M. Kellar

Tonnage 499 built at Renfrew When built 1865 10 ms.

By whom built Henderson Owners Geo. Lock & Wm. S. S. Co.

Port belonging to Glasgow Destined Voyage Glasgow Coast

If Surveyed Afloat or in Dry Dock On Todsell & Grogan Slip and a float

Last Survey, No. 9899 Port Iron. Classed A 1
S.S. Cl. No. 72. 3/72

REPAIRS, &c. In consequence of Damage by collision.

Four new plates on port bow. Five frames shifted with reverse frames. Three new side lights.

On Starboard Bow. Three new plates and one plate repaired. One beam arm repaired. Eleven frames with reverse frames properly shifted. A Shift of Waterway new. Several keel rivets renewed. Bottom coated with paint.

Present Condition of the

Decks	<u>Ironails</u> <u>Rivets</u>	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	<u>Copper</u> <u>Paint</u> When put on <u>1872</u>	Standing & Running Rigging
Engine Room Skylights <u>Good</u>	Caulking of	
Coal Bunker, Openings, Lids, &c. <u>Good</u>	Bottom, Deck, & Waterways <u>Good where seen</u>	
Scuppers <u>Good</u>		
Cargo and Main Hatchways <u>Good</u>		
Hatches <u>Good</u>		

General Observations and Opinion, Is now in good and efficient condition and fit to remain as classed

The Amount of Entry Fee.....£ 1 : " : " is received by me,

Special..... 4 : 4 : "

Certificate (if required) " : 5 : "

Committee's Minute 15th November 18 72

Character assigned A 1

period damage repair

T. W.



© 2019

Lloyd's Register Foundation