

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No. 23573** Survey held at **Liverpool** Date, first Survey **Nov-12** Last Survey **Nov-27** 18 **72**
 on the **"Smy Bengal"** Master **W. Code**
 Tonnage **1296** built at **Liverpool** When built **1868-1870**
 By whom built **Cloves** Owners **Clint & Co**
 Port belonging to **Liverpool** Destined Voyage **India**
 If Surveyed Afloat or in Dry Dock **Afloat - in Mr. Cloves' graving dock**
 Last Survey, No. **8518** Port **None** Classed ***-A-1**

REPAIRS, &c.

The Peeling equal to one strake & the lumber boards lifted both sides fore & aft - found the plate rivets & Cement in good condition, the foretopmast renewed of P Pine, & the hull scraped & painted where required -

Present Condition of the

Decks	Greenails Rivets	Windlass and Capstan Good & efficient
Waterways	Breasthooks and Stemson	Pumps " "
Comings	Transoms, Pointers, and Crutches	Boats " "
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c. " "
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained Seen from deck
Planksheers	Keelsons	Sails Good
Sheerstrakes	Clamps and Shelf's	Anchors No. of "
Topsides	Ceiling	Cables "
Wales	Rudder	Hawsers and Warps efficient
Plates (Bottom) and Counter	Copper Good When put on 60	Standing & Running Rigging when seen
Engine Room Skylights	Caulking of	Cargo and Main Hatchways Good
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways Good	Hatches Good
General Observations and Opinion,	Scuppers Good	

This Vessel is now in good Condition & in our opinion eligible to remain as Classed, & marked **S.A. No 1-72**

The Amount of Entry Fee.....£ : : is received by me,

Special..... 3 : 3 : "

Certificate (if required) : 5 :

Committee's Minute **Liverpool, 3rd December 1872**

Character assigned ***-A-1** **S.S. No 1-72**

REPORT OF SURVEY FOR

1885

"Bengal"

28513



Lloyd's Register Foundation