

Iron S.S. No 1 10966 32794
REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** Survey held at London Date, first Survey Dec^r 18th 1872 Last Survey Jan^r 9th 1873
 on the Y3^r "Catalina" (Iron) Master Ansuategui
 205 Tonnage 500 built at Sunduland When built 1868 11 mo
 By whom built _____ Owners Glurriaga & Co
 Port belonging to Bilboa Destined Voyage Havana
 If Surveyed Afloat or in Dry Dock Globe dry dock & London Dock
 Last Survey, No. 9278 Port Iron Classed *A 1

REPAIRS, &c.

8. 71
 Limber boards lifted, also nearly all the ceiling fore and aft of the flat; both surfaces of plating exposed, and the cement examined and repaired where required - The bottom outside painted with two coats of line and one of line & Tallow

Present Condition of the

Decks	} <u>Good</u>	Transoms	} <u>Good</u>	Windlass and Capstan	} <u>Sufficient</u>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Condition, how ascertained	
Planksheers		Keelsons		Sails	
Sheerstrakes		Clamps and Shelves		Anchors No. of	
Topsides		Ceiling		Cables	
Wales		Rudder		Hawsers and Warps	
Plank (Bottom) and Counter		Copper <u>When put on</u>		Standing & Running Rigging	
Engine Room Skylights	Caulking of				
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways	Scuppers	Cargo and Main Hatchways	Hatches	

General Observations and Opinion, good

This vessel is eligible in my opinion to remain as classed *A 1 and be marked (S.S. No. 1. 73)

The Amount of Entry Fee.....£ _____ is received by me,

Special..... 2 : 2 :

Certificate (if required) : 5 :

Committee's Minute London, 17th January 1873

Character assigned *A 1

S.S. No. 1-73
[Signature]

[Signature: Jos. M. Brown]



© 2019

Lloyd's Register Foundation