

ANNUAL SURVEYS.

Rec 23/4/73
1873

No. 49 Survey held at Hamburg Date 10th April
on the Barque John C. Munro Master John Smith
Tonnage 612 Built at Sunderland When built 1862. 11 mo
By whom built Laing Owners Killik Martin & Co
Port belonging to London Destined Voyage Hongkong
If Surveyed Afloat or in Dry Dock in floating dock

Last Survey, No. 45076 Port of London Iron Classed *A 1. 12. 71

S.S. No 2-71

The present Condition of the

Decks <u>good</u>	Treenails	Windlass and Capstan <u>good</u>
Waterways <u>wood & good</u>	Breasthooks and Stemson	Pumps <u>do</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches	Boats <u>all very good</u>
Upper Deck Beams & Fastenings <u>do</u>	Timbers of the Frame at the Openings	Masts, Yards, &c. <u>do</u>
Lower Deck Beams & Fastenings <u>very good</u>	Ditto ditto at other places	Sails <u>do</u>
Planksheers	Keelsons <u>good</u>	Anchors, No. of <u>do</u>
Sheerstrakes <u>good</u>	Clamps and Shelves	Cables <u>do</u>
Topsides	Ceiling <u>good</u>	Hawsers and Warps <u>do</u>
Wales	Rudder <u>do</u>	Standing and Running Rigging <u>broken</u>
Plank (Bottom) and Counter	Copper When put on	

General Observations and Opinion, very good Caulking of Bottom, Deck, and Waterways

She is in a very good condition and new repainted in and out side. Certificate wanted

Committee's Minute 25th April. 1873

Character assigned *A 1

Emil Laddatz

5/ Certificate (if required).

No. Survey held at Date 18
on the Master
Tonnage Built at When built
By whom built Owners
Port belonging to Destined Voyage
If Surveyed Afloat or in Dry Dock

Last Survey, No. Port of Classed

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors, No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing and Running Rigging
Plank (Bottom) and Counter	Copper When put on	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Committee's Minute 18

Character assigned



© 2019

Lloyd's Register
Foundation
Certificate (if required).