

Iron. 11323 REPORT of SURVEY for REPAIRS.

Rec 12/5/73

No. in Reg. Book. 277 No. 10576 Survey held at Sunderland Date, first Survey Dec 20 Last Survey Dec 20 1873
on the Scm "Celsus" Master R. Thompson
Tonnage 1007 built at Sunderland When built 1871. 9mo
By whom built Thompson Owners Gulliford and Co.
Port belonging to Sunderland Destined Voyage Alexandria
If Surveyed Afloat or in Dry Dock Cornhill dry Dock

Last Survey, No. 9968 10245 Port Sunderland Droit Sunderland Classed 90.A.1
3.72

REPAIRS, &c. Now done, on account of encountering a severe storm

The Bottom Cleaned, Several rivets removed, and renewed at the flat and bilges, and several butts caulked in the same neighbourhood; the Cement repaired &c. where rivets &c. were removed; the Man holes to Tanks removed, Floors &c examined both at the timbers and in the Tanks as far as practicable.

Payed. the Bottom with three coats of Paint

The upper Gudgeon to Rudder being broken was removed and an iron Strap substituted.

Present Condition of the

Decks	<u>Good</u>	Keelsons	<u>Good</u>	Windlass and Capstan	<u>Good</u>
Waterways	<u>Gutter funnel</u> <u>Do</u>	Breasthooks and Stemson	<u>good</u>	Pumps	<u>Do</u>
Comings	<u>Do</u>	Transoms, Potlocks and Crutches	<u>good</u>	Boats	<u>Do</u>
Upper Deck Beams & Fastenings	<u>Do</u>	Timbers of the Frame at the openings	<u>Do</u>	Masts, Yards, &c.	<u>Do</u>
Lower Deck Beams & Fastenings	<u>Do</u>	Ditto Ditto at other places	<u>Do</u>	Condition, how ascertained	<u>inspⁿ and enquiry</u>
Planksheers	<u>Do</u>	Keelsons	<u>Do</u>	Sails	
Sheerstrakes	<u>Do</u>	Clamps and Shells		Anchors	No. of <u>3 B/W. 2 K.</u> <u>good</u>
Topsides	<u>Do</u>	Ceiling	<u>Do</u>	Cables	
Wales	<u>Do</u>	Rudder <u>new up^{1/2} fudgeon</u> <u>Do</u>		Hawsers and Warps	
Plank (Bottom) and Counter	<u>Do</u>	Copper <u>paint</u> When put on <u>now</u>		Standing & Running Rigging	<u>Good</u>
Engine Room Skylights	<u>Good</u>	Caulking of		Cargo and Main Hatchways	<u>good</u>
Coal Bunker, Openings, Lids, &c.	<u>good</u>	Bottom, Deck, & Waterways	<u>Good</u>	Hatches	<u>good</u>
Scuppers	<u>good</u>				

General Observations and Opinion,

She is now in good and efficient condition and fit in my opinion to remain as Classed Vix 90A.1.

Joseph New.

The Amount of Entry Fee.....£ : : is received by me,

Special..... 2 : 2 : 0

Certificate (if required) : :

Committee's Minute 13th May 1873.

Character assigned

90A.1
IFW