

# REPORT of SURVEY for REPAIRS.

1146w  
Recd 11/10/72

No. in Reg. Book. **No.** 3104 Survey held at West Hartlepool Date, first Survey 30<sup>th</sup> Sept Last Survey 2<sup>nd</sup> Oct. 18 72  
 on the S.S. "May Queen" Master J. J. Mansel  
 Tonnage 595 built at London When built 1864  
 By whom built Lingley Owners Gen. J. S. Row Col. Co.  
 Port belonging to London Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock In Dry Dock

Last Survey, No. 11009 Port Iron Classed 90 A1

## REPAIRS, &c.

This vessel has been stranded on the Longspear Rocks in Hartlepool Bay, the bottom on the Port side being very much damaged, 26 plates badly bent & one broken through, several frames & bulges broken, the owners having a desire to have the repairs done in London, she has now been temporarily repaired for the purpose of proceeding to the Commercial Dock in that Port.

J. P. Gladstone  
James M. Neil

## Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper When put on	Standing & Running Rigging
Engine Room Skylights	Caulking of	
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways	
General Observations and Opinion,	Scuppers	Cargo and Main Hatchways
		Hatches

The Amount of Entry Fee.....£ - : - is received by me,

Special.....2 : 2 : 0

Certificate (if required) : :

Committee's Minute 18

Character assigned