

# REPORT of SURVEY for REPAIRS.

11507

~~23108~~

No. in Reg. Book. **No.** Survey held at London Date, first Survey 28<sup>th</sup> May Last Survey 4<sup>th</sup> June 1873  
 on the Seren 2<sup>nd</sup> Europa Master J. Campbell  
 Tonnage 676 built at Newcastle When built 1862 - 3mo  
 By whom built Palmer Owners Lord 2<sup>nd</sup> Ship Comp<sup>y</sup> Lim<sup>d</sup>  
 Port belonging to London Destined Voyage Mediterranean  
 If Surveyed Afloat or in Dry Dock On the Victoria Dock Butoon  
 Last Survey, No. 10299 Port Iron Classed 95 A  
 REPAIRS, &c. 5.5 Mc<sup>2</sup> 462-70, 6.72

Caulked butts of bottom plating; rudder joints repaired, the bottom cleaned and coated with Paint. Inside chipped, and beaten clean, and painted throughout

## Present Condition of the

Decks <u>Good</u>	Keelsons <u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>Good</u>	Breasthooks and Stemson <u>Good</u>	Pumps <u>Good</u>
Comings <u>Good</u>	Transoms, Pointers, and Crutches <u>Good</u>	Boats <u>Good</u>
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame at the openings <u>Good</u>	Masts, Yards, &c. <u>Good</u>
Lower Deck Beams & Fastenings <u>Good</u>	Ditto Ditto at other places <u>Good</u>	Condition, how ascertained <u>Seen from the deck</u>
Planksheers <u>Good</u>	Clamps and Shells <u>Good</u>	Sails <u>Good and sufficient</u>
Sheerstrakes <u>Good</u>	Ceiling <u>Good</u>	Anchors No. of <u>3 13 15 24</u>
Topsides <u>Good</u>	Rudder <u>Good</u>	Cables <u>Good</u>
Wales <u>Good</u>	Copper <u>Good</u>	Hawsers and Warps <u>Good</u>
Plank (Bottom) and Counter <u>Good</u>	Caulking of <u>3 good where</u>	Standing & Running Rigging <u>Good</u>
Engine Room Skylights <u>Good</u>	Bottom, Deck, & Waterways <u>Examined</u>	Cargo and Main Hatchways <u>Good</u>
Coal Bunker, Openings, Lids, &c. <u>Good</u>	Scuppers <u>Good</u>	Hatches <u>Good</u>

General Observations and Opinion,

Is now in good and efficient condition, and in my opinion eligible to remain as classed.

*H. Turner*

The Amount of Entry Fee.....£..... is received by me,

Special.....

Certificate (if required) .....

Committee's Minute 20<sup>th</sup> June 1873

Character assigned 95 A

*TRW*



© 2019

Lloyd's Register Foundation

IRON454-0255