

REPORT of SURVEY for REPAIRS.

11950.

Rec 31/10/73

No. in Reg. Book. **No. 4231** Survey held at **Hull** Date, first Survey **4th Sept** Last Survey **5th Sept** 18**73**
 on the **Iron Sloop The Yorkistall** Master **Dudding**
 Tonnage **470** built at **Northfleet** When built **1870**
 By whom built **320 Allibon Noyes & Co** Owners **B & Son Yorkshires Steam Ship Comp**
 Port belonging to **London** Destined Voyage **Coasting**
 If Surveyed Afloat or in Dry Dock **On Bailey & Leatham slip way**
 Last Survey, No. **455** Port **Iron** Classed **△ \ 1170**

REPAIRS, &c.

Now done - The outside plating from the keel to the gunwale scraped clean & painted

*Manuscript Survey
see letter attached
28/10/73*

Present Condition of the

Decks	Freemasts <i>knobs</i>	Windlass and Capstan
Waterways	Breasthooks and Stenson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper When put on	Standing & Running Rigging
Engine Room Skylights	Caulking of	
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways	
Scuppers		
Cargo and Main Hatchways		
Hatches		

General Observations and Opinion,

This vessel when seen appeared in good condition & the Master stated all the stores were complete

M Davidson

The Amount of Entry Fee.....£ — : — is received by me,
 Special..... — : —
 Certificate (if required) — : —

Committee's Minute _____ 18____
 Character assigned _____

