

~~12926~~ 12926

Rec 5/7/70

22

This Vessel has received the following Repairs owing to defects.

S. J. N^o 3. 66.

Decks

Frank

Reit

Lord

Windlass and

Breasthooks and Stemson

Pumps

Transoms, Pointers, and Crutches

Boats

~~Timbers of the~~ Frame at the openings.

Masts, Yards, &c.

Kilgus

Condition, how ascertained

Clamps and Shelves

Sails

Ceiling

Anchor

Rudder

Cables

—

Hawse

Bottom, Deck, & Waterways

Standing & Running Rigging

Coal Bunker, Openings, Lids, &c.

venings, Lids, &c.

Wood Scuppers

Good

Cargo and Main Hatchway

8 1272

Hatches

This Vessel has had considerable repairs, and all Ceiling & and plating scraped. The original frames, plating, and deck wasted by oxidation, and the Vessel is ineligible for A 1 for Race purposes, and for which I demand her. S. P. R^o 5 - 74

Special..... 4 : 4 : 0

Special..... 4 : 4 : 0

Certificate (if required)

Committee's Minute

Character assigned

Reduced to

18

Thomas Conydon

² Henry Follett

This vessel appears eligible
for the Class recommended by
A.S. for River Navigation
7/19/74

Sub. Committee 3rd Sept. 1874

To be Classed ~~As~~ 1

~~S.S. 78~~

S.S. (No. 3-74)

(Not
for River Survey only)



© 2019

Lloyd's Register
Foundation