

13398.

34232

## REPORT of SURVEY for REPAIRS, &amp;c.

No. in Reg. Book. *No.* Survey held at *London* Date, first Survey *Nov 5<sup>th</sup>* Last Survey *Nov 5<sup>th</sup>* 18*74*  
 on the *Ship "Aurora"* Master *A. Johnston*  
*not yet in Reg. Bk.* Tonnage *1857* built at *Greenock* When built *1874*  
 By whom built \_\_\_\_\_ Owners *Anderson & Anderson*  
 Port belonging to *London* Destined Voyage *Adelaide Sept<sup>r</sup> Ind. Reg<sup>d</sup>*  
 If Surveyed Afloat or in Dry Dock *South West India Dock*

Last Survey, No. *133904* Port *Iron* *Not* Classed

REPAIRS, OR EXAMINATION AS PER RULE

*The shaft of this vessels patent Capstan, in connection with the windlass, has been renewed, and the windlass is now in perfect working order.*

## Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams &amp; Fastenings

Lower Deck Beams &amp; Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the openings

Ditto Ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper

When put on

Caulking of

Bottom, Deck, &amp; Waterways

Windlass and Capstan

Pumps

Boats

Masts, Yards, &amp;c.

Condition, how ascertained

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing &amp; Running Rigging

Engine Room Skylights

Coal Bunker, Openings, Lids, &amp;c.

Scuppers

Cargo and Main Hatchways

Hatches

General Observations, Opinion as to Class, &amp;c.

The Amount of Entry Fee ... ..£ : : received by me, }  
 Special ... ..£ : : 187 }  
 Certificate (if required) ... ..£ : :

(Travelling Expenses, if any, £)

Committee's Minute *6<sup>th</sup> November 1874*Character assigned *100A**T. Johnston*

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

Lloyd's Register  
Foundation

180459-0009