

# REPORT of SURVEY for REPAIRS.

13412

Rec 10/10/74

No. in Reg. Book. **No. 52** Survey held at Sydney Date, first Survey 18 May Last Survey 30 June 1874  
 on the Ship British India Master Coxon  
 Tonnage 1199 built at Couper's When built 1864-12mo  
 By whom built Laid Owners British Ship Owners Co.  
 Port belonging to Liverpool Destined Voyage California  
 If Surveyed Afloat or in Dry Dock in dry dock and afloat

Last Survey, No. 12335 Port Iron Classed — A1  
 S.S. Lon No. 2-34154

REPAIRS, &c.

Locked. Rudders unshipped, repaired & altered  
 new Rudder & fudgeon. new Sheffing box & collar for  
 Rudder head & was in. new Jibboom. Head Rails.  
 Dolphin Shivers. and headgear

ion of the

Comings	Good	Greenails	Drivelling	Good	Windlass and Capstan	Good
Upper Deck Beams & Fastenings	Dr	Breasthooks and Stemson	Dr		Pumps	Dr
Lower Deck Beams & Fastenings	Dr	Transoms, Pointers, and Crutches	Dr		Boats	Dr
Planksheers	Dr	Timbers of the Frame at the openings	Dr		Masts, Yards, &c.	Dr
Sheerstrakes	Dr	Ditto Ditto at other places	Dr		Condition, how ascertained	Dr
Topsides	Dr	Keelsons	Dr		Sails	full & complete outfit
Wales	Dr	Clamps and Shelves	Dr		Anchors	No. of 3 B. 1 B. 2 Ridges
Plank (Bottom) and Counter	Dr	Ceiling	Dr		Cables	full length & size
Engine Room Skylights	Dr	Rudder	Dr		Hawsers and Warps	thin & good
Coal Bunker, Openings, Lids, &c.	Dr	Copper	When put on		Standing & Running Rigging	Dr
Scuppers	Good	Caulking of			Cargo and Main Hatchways	Good
Hatches	Good	Bottom, Deck, & Waterways	Good			

General Observations and Opinion,

It is reported that this vessel has on more than one occasion  
 had similar accident to her Rudder & steering gear. which I attribute  
 to its excessive width and bad shape. I have now reduced it 10 or 12 inches  
 and altered the shape. and had the pen. m. as efficiently & centered than they  
 were originally

The Amount of Entry Fee.....£ : : is received by me,

Special..... : :

Certificate (if required) : :

Committee's Minute 20<sup>th</sup> October 1874

Character assigned



© 2019

Lloyd's Register  
 Foundation

180N459-0026