

SS No 2 Survey more than due & the owners decline to have her surveyed 13587. 34297

REPORT of SURVEY for REPAIRS, &c.

No. in Reg. Book. No. 170 Survey held at London Date, first Survey Nov 6 1874 Last Survey Nov 20 1874

on the Lion P.S. Harwich Master

| | | | |
|------------------------------------|---|-----------------|--------------|
| TONNAGE and Tonnage Deck | Built at London | When built 1864 | YEAR. MONTH. |
| Ditto of Spar Deck, or Awning Deck | | | 5 |
| Ditto of Deck, or Raised Qr. Dk. | Owners E. J. Eastern Railway & Port belonging to London | | |
| Ditto of Houses on Deck | Residence W. Rivers Manager Harwich | | |
| Ditto of Forecastle | By whom built Simpson | Destined Voyage | |
| Gross Tonnage 750 | If Surveyed Afloat or in Dry Dock Dry Dock | | |
| Crew Space, as per Rule | | | |
| Register Tonnage, cut on Beam | | | |
| Engine Room | | | |
| Reg. Tons as St' mer, cut on Bm. | | | |

Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft.

Last Survey, No. 11456 Port Classed B 9.70 SS No 68

REPAIRS, OR EXAMINATION AS PER RULE

SS No 2 Survey is more than due in this case and I wrote to the Owners acquainting them of the same, by the accompanying letter it appears they dont intend to conform to the Rules, I examined the outside of the ship in leaving dock and a small part of the inside and she appeared in good condition so far as she could be seen.

Cause of Repairs to be clearly stated.

| | | | |
|--|--------------------------------------|----------------------------|--|
| Present Condition of the | | | |
| Decks | Treenails | Windlass and Capstan | |
| Waterways | Breasthooks and Stemson | Pumps | |
| Comings | Transoms, Pointers, and Crutches | Boats | |
| Upper Deck Beams & Fastenings | Timbers of the Frame at the openings | Masts, Yards, &c. | |
| Lower Deck Beams & Fastenings | Ditto Ditto at other places | Condition, how ascertained | |
| Planksheers | Keelsons | Sails | |
| Sheerstrakes | Clamps and Shelves | Anchors No. of | |
| Topsides | Ceiling | Cables | |
| Wales | Rudder | Hawsers and Warps | |
| Plank (Bottom) and Counter | Copper When put on | Standing & Running Rigging | |
| Engine Room Skylights | Caulking of | | |
| Coal Bunker, Openings, Lids, &c. | Bottom, Deck, & Waterways | | |
| Scuppers | | | |
| Cargo and Main Hatchways | | | |
| Hatches | | | |
| General Observations, Opinion as to Class, &c. | | | |

In reference to what is stated above I respectfully leave the case in the hands of the Committee
Saml. House Martindale

The Amount of Entry Fee ... £ : : received by me, }
Special ... £ : : 187 }
Certificate (if required) ... £ : :
(Travelling Expenses, if any, £)

Committee's Minute 11th December 1874

Character assigned Exempt Character
Omit Character for representing Lloyd's Register
Paul. Corro. J. B. W. The Register Books H. B. W. Write to owner

The Surveyors are requested not to write on or below the space for Committee's Minute.

2420459-0242

General Committee Minutes

17th Dec - 1874

Expense Character

to 18/12/74

B.M.



© 2019

Lloyd's Register
Foundation