

13706

## REPORT of SURVEY for REPAIRS, &amp;c.

No. in Reg. Book. *No. 11010* Survey held at *Sunderland* Date, first Survey *January 8<sup>th</sup>* Last Survey *January 9<sup>th</sup> 1875*  
 on the *B.K. "Guz"* Master *Wm Hatch*

Tonnage *420* built at *Sunderland* When built *1864. (11 mo)*

By whom built *Laing* Owners *R. Weatherly*

Port belonging to *Sunderland* Destined Voyage

If Surveyed Afloat or in Dry Dock *Arthur's Dry Dock*

Last Survey, No. *12133* *10438* Port *Sunderland* *Iron*

Classed

Years assigned.

Character in Register Book.

A 1

12/3

S.B. Hd. No. 1-1/3

REPAIRS, OR EXAMINATION AS PER RULE

*Annual Survey*

*Sighted Bottom, cleaned, payed with two coats of Lead and one of Yellow for the timbers and a portion of ceiling lifted in each Hold and found the Floors, Ribs, frames, plates, Beams, &c. &c. where seen; in good condition, and the Cement satisfactorily adhering to the Bottom plating, &c.*

Cause of Repairs to be clearly stated.

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams &amp; Fastenings

Lower Deck Beams &amp; Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

Coal Bunker, Openings, Lids, &amp;c.

Scuppers

Windlass and Capstan

Pumps

Boats

Masts, Yards, &amp;c.

Condition, how ascertained

Sails

Anchors

Cables

Hawsers and Warps

Standing &amp; Running Rigging

Cargo and Main Hatchways

Hatches

General Observations, Opinion as to Class, &amp;c.

*She is now in good and efficient condition and fit in my opinion to remain as Classed viz. A. 1.*

The Amount of Entry Fee ... £ ... received by me, *14 Jan 1875*

Special ... £ ...

Certificate (if required) ... £ ...

(Travelling Expenses, if any, £ ...)

Committee's Minute

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

Lloyd's Register Foundation

IRON659-0386