

13833

REPORT of SURVEY for REPAIRS, &c.

No. in
Reg. Book.

No. 11033

Survey held at SunderlandDate, first Survey January 11thLast Survey January 29th 1875

Rec 15/2/75

on the Barge"Ismay"Master Alex PattieTonnage 422.47 built at GlasgowWhen built 1861 - 4 moBy whom built StephenOwners J. W. Robertson, Dundee, County of ForfarPort belonging to LiverpoolDestined Voyage Valparaiso

If Surveyed Afloat & in Dry Dock

S. G. DockLast Survey, No. 12797Port Liverpool

Classed

S.S. Lon No 2-30 8.32

REPAIRS, OR EXAMINATION AS PER RULE Survey No. 3

Cause of Repairs to be clearly stated.

Now done, The vessel laid upon blocks; the hold cleared, and all the close ceiling removed; the inner and outer surfaces of shell plating, the frames, stringers, hooks, floor plates, keelsons &c exposed; about 30 holes drilled in the shell plating and upper deck stringer plates; the windlass unhooking & wood linings stripped and the chain cables ranged on deck and found good and sufficient. The cement in the flat of bottom is found to be adhering very satisfactorily to the iron and after all oxidation had been removed, no diminution in thickness of material could be observed; The hatches repaired, and the outer surface of plating coated with 2 coats of paint, & the inner surface painted throughout; Hatches and cement-repaired

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

Coal Bunker, Openings, Lids, &c.

Scuppers

Cargo and Main Hatchways

Hatches

General Observations, Opinion as to Class, &c.

Frames

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the openings

Ditto Ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Cement When put on

Caulking of

Bottom, Deck, & Waterways

Windlass and Capstan

Pumps 2 Metal

Boats 3 1/2

Masts, Yards, &c. Ex: where

Condition, how ascertained

Sails

Anchors No. of 33, 15, 2 K

Cables 240 fath: 1 1/2 & 1 1/4

Hawsers and Warps

Standing & Running Rigging

The Amount of Entry Fee£

Special£

Certificate (if required)£

(Travelling Expenses, if any, £)

Committee's Minute

16th February

1875

Character assigned

received by me,

15 Feb 1875

Surveyor to Lloyd's Register of British and Foreign Shipping.

© 2019

Lloyd's Register
Foundation

IRON 460-0087