

ANNUAL SURVEYS.

114252

34687

No. in Reg. Book. on the 604 No. 1156.26 Survey held at London Date, first Survey 21 April Last Survey 21 April 1875

Master British Monarch Built at Riverhead When built 1865 4 mcs.
By whom built Owner Owners British Ship Owners Co.

Port belonging to Spain Destined Voyage Dry dock

If Surveyed Afloat or in Dry Dock Dry dock
Last Survey, No. 12692 Port of Port Spain

Classed Δ1 Character in Register Book. 5.74
S.S. 2-2.74

Present Condition of the Decks Waterways Comings Upper Deck Beams & Fastenings Lower Deck Beams & Fastenings Planksheers Sheerstrakes Topsides Wales Plank (Bottom) and Counter Engine Room Skylights General Observations, Opinion as to Class, &c.	Treennails <u>Rivets</u> Breasthooks and Stemson Transoms, Pointers, and Crutches Timbers of the Frame at the Openings Ditto ditto at other places Keelsons Clamps and Shelves Ceiling Rudder Copper or Y.M. When put on Caulking of Bottom, Deck, & Waterways Coal Bunker, Openings, Lids, &c. Scuppers	Windlass and Capstan <u>Good</u> Pumps <u>Good</u> Boats <u>Good</u> Masts, Yards, &c. Condition, how ascertained <u>from deck</u> Sails <u>well found</u> Anchors, No. of <u>3 1/2 1/2 & Hedge</u> Cables <u>Complete</u> Hawsers and Warps <u>Suffice</u> Standing and Running Rigging <u>Good</u> Cargo and Main Hatchways <u>Good</u> Hatches <u>Good</u>
---	--	---

Bottom scraped and recanted. Rudder repaired. This ship appears in good condition and eligible to remain as classed.

Committee's Minute 27th April 1875 Character assigned Δ1
 Surveyor to Lloyd's Register of British and Foreign Shipping. J.D.M.
 Certificate (if required) Paid _____ 18 _____

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18 _____
 No. in Reg. Book. on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____
 Present Condition of the Decks
 Waterways
 Comings
 Upper Deck Beams & Fastenings
 Lower Deck Beams & Fastenings
 Planksheers
 Sheerstrakes
 Topsides
 Wales
 Plank (Bottom) and Counter
 Engine Room Skylights
 General Observations, Opinion as to Class, &c.

Treennails Breasthooks and Stemson Transoms, Pointers, and Crutches Timbers of the Frame at the Openings Ditto ditto at other places Keelsons Clamps and Shelves Ceiling Rudder Copper or Y.M. When put on Caulking of Bottom, Deck, & Waterways Coal Bunkers, Openings, Lids, &c. Scuppers	Windlass and Capstan Pumps Boats Masts, Yards, &c. Condition, how ascertained Sails Anchors, No. of Cables Hawsers and Warps Standing and Running Rigging Cargo and Main Hatchways Hatches
---	---

Committee's Minute _____ 18 _____ Character assigned _____
 Surveyor to Lloyd's Register of British and Foreign Shipping. _____
 Certificate (if required) Paid _____ 18 _____



ALPHABETICALLY

21

Printed Records



© 2019

Lloyd's Register
Foundation