

REPORT of SURVEY for REPAIRS, &c.

(Received 22nd April 1875)

No. in Reg. Book. **No. 12011** Survey held at **Newcastle** Date, first Survey **19th** Last Survey **30th March 1875**

67 on the **S.S. "James Joyce"** Master **G. Monnell**

Official Number **423**
 TONNAGE under Tonnage Deck **645**
 Ditto of Spar Deck, or Awaiting Deck
 Ditto of ~~Deck~~ Raised or. Dk. **49**
 Ditto of Houses on Deck
 Ditto of Forecastle
 Gross Tonnage **695**
 Crew Space, as per Rule
 Register Tonnage, out on Beam
 Engine Room **159**
 Reg. Tons as St'ner, out on Bm. **536**
 Built at **Newcastle** When built **1863** MONTH. **5**
 Owners **J. Fenwick & Co** Port belonging to **London**
 Residence **London**
 By whom built **Palmer** Destined Voyage
 If Surveyed Afloat or in Dry Dock **Afloat**

Length of Poop **ft.** Ditto, Forecastle **ft.** Ditto, Raised Quarter Deck **ft.**
 Last Survey, No. **13140** Port **Iron** Classified **A 1**
 Character in Register Book. **8.44**

REPAIRS, OR EXAMINATION AS PER RULE **Repair of Damage** S.S. **Lon No 2-74**

Now done on account of collision. - Nine plates on port bow renewed. - two broken frames & reverse frames repaired. - One main deck & one lower deck beam repaired. - foremast plate of lower deck stringer renewed, upper turn Nelson in way of the broken plates repaired & breasthook on same renewed. Port house pipe renewed & main deck from fore end of fore hatch to the stem recaulked.

Present Condition of the	<i>find</i>	<i>find</i>	<i>find</i>
Decks	<i>find</i>	<i>find</i>	<i>find</i>
Waterways	<i>find</i>	<i>find</i>	<i>find</i>
Comings	<i>find</i>	<i>find</i>	<i>find</i>
Upper Deck Beams & Fastenings	<i>find</i>	<i>find</i>	<i>find</i>
Lower Deck Beams & Fastenings	<i>find</i>	<i>find</i>	<i>find</i>
Planksheers	<i>find</i>	<i>find</i>	<i>find</i>
Sheerstrakes	<i>find</i>	<i>find</i>	<i>find</i>
Topsides	<i>find</i>	<i>find</i>	<i>find</i>
Wales	<i>find</i>	<i>find</i>	<i>find</i>
Plank (Bottom) and Counter	<i>find</i>	<i>find</i>	<i>find</i>
Engine Room Skylights	<i>find</i>	<i>find</i>	<i>find</i>
Coal Bunker, Openings, Lids, &c.	<i>find</i>	<i>find</i>	<i>find</i>
General Observations, Opinion as to Class, &c.	<i>find</i>	<i>find</i>	<i>find</i>

This vessel has been efficiently repaired & being now in find condition is eligible in my opinion to remain as classed A 1.

The Amount of Entry Fee ... £ 2 : : : received by me,
 Special ... £ 2 : 2 : : 21 Apr 1875
 Certificate (if required) ... £ 4 : 4 : :
 (Travelling Expenses, if any, £)

Committee's Minute **23rd April 1875**

Character assigned

By your Obedt. Servant
 Surveyor to Lloyd's Register of British and Foreign Shipping.