

ANNUAL SURVEYS.

34.6.75

Recd 24-6-75

No. 432 Survey held at London Date June 15 1875
 on the Iron S. Hesperalaya Master _____
 Tonnage 1008 Built at Sunderland When built 1863 11M
 By whom built W. Pile Owners Shaw Savill & Co
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock By Sea

Last Survey, No. 12082 Port of Iron Classed *A/ 11.73
SS Sen No 73

The present Condition of the

Decks	<u>Good</u>	Treenails <u>Rivet</u>	<u>Good</u>	Windlass and Capstan	
Waterways	"	Breasthooks and Stemson	"	Pumps	
Comings	"	Transoms, Pointers, and Crutches	"	Boats	
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	Masts, Yards, &c.	<u>Good</u>
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	Sails	<u>and</u>
Planksheers	"	Keelsons	"	Anchors, No. of <u>3 Bro. & 2 Vels</u>	<u>Sufficient</u>
Sheerstrakes	"	Clamps and Shelves	"	Cables	<u>where</u>
Topsides	"	Ceiling	"	Hawsers and Warps	<u>the could</u>
Wales	"	Rudder	"	Standing and Running Rigging	<u>be seen</u>
Hulk (Bottom) and Counter	"	Copper <u>Painted</u> When put on <u>Now</u>			

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good

at present the bottom Scraped Painted & Coated
 She is now in a efficient state of repair
 and entitled to remain as classed

Committee's Minute

29th June 1875

Senhouse Martindale

Character assigned

TRW

Certificate (if required).

No. 84 Survey held at London Date June 14 1875
 on the Iron S. Saint Maur Master Murray
 Tonnage Tonnage attached Built at Liverpool When built 1858
 By whom built _____ Owners Rankin & Co. & Jardine
 Port belonging to Liverpool Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Pontoon

Last Survey, No. 13112 Port of Iron Classed *A/ 7.74
SS Sen No 3.74

The present Condition of the

Decks	<u>Good</u>	Treenails <u>Rivet</u>	<u>Good</u>	Windlass and Capstan	
Waterways	"	Breasthooks and Stemson	"	Pumps	
Comings	"	Transoms, Pointers, and Crutches	"	Boats	
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	Masts, Yards, &c.	<u>Good</u>
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	Sails	<u>and</u>
Planksheers	"	Keelsons	"	Anchors, No. of <u>3 Bro. & 2 Vels</u>	<u>Sufficient</u>
Sheerstrakes	"	Clamps and Shelves	"	Cables	<u>where</u>
Topsides	"	Ceiling	"	Hawsers and Warps	<u>they could</u>
Wales	"	Rudder	"	Standing and Running Rigging	<u>be seen</u>
Plank (Bottom) and Counter	"	Copper <u>Painted</u> When put on <u>Now</u>			

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good

at present the bottom Scraped Painted & Coated
 She is now in an efficient state of repair
 and entitled to remain as classed

Committee's Minute

29th June 1875

Senhouse Martindale

Character assigned

TRW

Certificate (if required).